

(attachment & enclosure)

Store Action:

If the Remington Model 710 gun box has a round yellow label with the letters SDS on the box end label, the gun is NOT part of the recall. The gun should be put on the shelf and made available for sale. If you have any Remington Model 710 guns without the round yellow label, please call Remington Arms company, Inc. @ 1-800-243-9700 with the serial numbers of the Model 710 firearm and they will advise if the gun is part of the recall. If it is, they will advise on the proper way to have the gun evaluated and serviced.

Additionally, please provide consumer contact information (name, address, phone # and serial #) to Remington @ 800-243-9700 on all model 710's you have sold since August 1, 2002. Remington will contact the customer and ensure that the firearm is appropriately serviced.

(picture needs to be inserted)

Mayfield product/Parts update timeline

Model 710

- Nov, 2000 Added to Quality team meetings
- Jan, 2001 Changed braze for bolt handle. First 7000-8000 guns braze was incorrect, resulting in the handle separating from the bolt body
- Feb, 2001 710 Update program started
 - changed finish on bolt body to decrease OD
 - added 2 nylon ribs between receiver & insert
- Mar, 2001 Email response for bolt finish/binding
We apologize for any misunderstanding. There is not a recall on the Model 710. However, we have discovered an incorrect finish on the bolt of the first shipment of this model. The incorrect finish can cause the bolt to bind when the action is cycled. We are performing an update to correct this finish, however this is strictly voluntary. This is not a recall, and there are absolutely no safety concerns. This is only for function and ease of operation. Again, we apologize for any inconvenience. If you have further questions, please feel free to call us at 1-800-243-9700.
- Aug, 2001 Added bolt stop spring, and changed inlet in stock to accommodate (starting with serial #71025377)
- Aug, 2001 Burris Optics introduced scope mounts for the Model 710. part number 410270 / 2 piece base, matte finish / Burris's phone number 1-888-228-7747
- Jan, 2002 Hardened bolt stop material to stop them from shearing off