

Draft - -December 9,2002

PRIVILEGED & CONFIDENTIAL
ATTORNEY WORK PRODUCT

Remington Model 710

**PRODUCT SAFETY WARNING AND RECALL
NOTICE**

Remington Arms Company, Inc. is voluntarily recalling a limited number of **Model 710® bolt-action rifles manufactured between July and October 2002** which may have been assembled with an improperly made "Safety Detent Spring." Although unlikely, there is a possibility that the manual safety arm mechanism in such a rifle could fail to fully return to the "safe" or "on" position.

WARNING: STOP USING YOUR RIFLE IMMEDIATELY. Use of a rifle with an improperly functioning safety could lead to an accidental discharge, resulting in personal injury, death or property damage.

To determine if your model 710 rifle is subject to this recall you should contact Remington immediately by calling **1-800 243-9700, or 336 548-8700 Monday through Friday 9 AM – 5PM EST.** Remington will assist you in making arrangement to have your rifle inspected and/or repaired by a Remington Authorized Repair Center at no charge to you. To expedite repair program, Remington will send shipping tags to each customer and will cover all related shipping and repair charges. **Please do not** return your rifle to a Remington Authorized Repair Facility before contacting Remington on the toll-free hotline.

Remington Arms Company, Inc.

Safety and safe firearms handling is everyone's responsibility.

21431772v2