

Over and Unders

Our over and under ONLY comes in 12 gauge.

Over and unders-break action-are the oldest modern shotguns.

332 will look basically like the 300.

All parts must stay with the same gun. **CAN'T INTERCHANGE!**
If they need a new bbl set they must send in all bbl sets so that the repairman can make the fore end and all other parts work with the new and old.

The receiver is called the frame on these guns.

These have a mechanical (not inertia) trigger.

This is a field gun but you can shoot trap or sport with it.

Trouble shooting

One bbl not going off-This can be caused by overlock. If the operating handle gets over to the left then the bolt and or other parts are getting worn. (The operating handle to the right is OK.)

Peerless and 396 were the last really good over and under that we made. We are still working on them in the repair shop.

These guns show wear around the bolt. Sometimes they sink in. This will cause the gun not to fire.

One thing that causes the above condition is using ammo with a steel firing pin such as Federal. **WE RECOMMEND THAT CONSUMERS NEVER USE STEEL PRIMERS!!!!!!**

DO NOT DRY FIRE AN OVER AND UNDER! THIS IS BAD FOR THE FIRING PINS.

A 26" bbl on an L100 will be longer than a 26" over and under. The over and under has a very short frame.

If the wood to metal fit isn't correct then the stock will crack.

The higher rated wood (ex. F) is more easy to crack.