

Wetmore Co., Inc.

NO GUN EXAMINATION REPORT NUMBER: _____

MODEL: 700 ADL

GENERAL CONDITION: NEW

R # : 24301

OUTSIDE WORK: NO

DATE: 12-13-71

FIRE AMMO TYPE: -

FROM: JENSEN BYRD CO.

SPokane, WASH.

& CONDITION: _____

GUN # : 6411367

PROOF: R.I.P.-1 INSP.: 55 TEST: 49

CODE: AU-3/71

HEADING: O.K.

GA./CAL.: 300G

BREECH OPENING: -

CHECKED BY: C. PROSSER

RECOIL SHOULDERS: O.K.

APPROVED: _____

CHAMBER: O.K.

APPROVED: _____

TEST: NO

APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style)

APPROVED: _____

NO DAMAGED BROKEN COMPONENTS. TRIGGER PULL SEHS-
TRIGGER CONNECTOR ENGAGEMENT AND SEHS-FRAME PIN
HEAD ENGAGEMENT WITHIN SPECIFICATIONS. TRIGGER CLEAR
TRIGGER GUARD.

COMPLAINT: FIRES WHEN BOLT IS CLOSED

INCIDENT: FOLLOW DOWN

**PLAINTIFF'S
EXHIBIT**

3265

COMMENTS: THE CUSTOMER'S MALFUNCTION CANNOT BE DUPLICAT-
ED. SOME FOREIGN MATERIAL IS NOTED ON THE TRIGGER
CONNECTOR WHICH MAY HAVE CAUSED IT TO STICK IN
FIRE POSITION, RESULTING IN A FOLLOW DOWN.