

			NOT FEEDING OR EXTRACTING AMMO	TIME.
KY	597	A2627833		11-00
KY	597	I2750170	GUN JAMS.	05-99
KY	597	A2636408	ACTION SQUEAKS.	01-01
KY	597	A2636541	JAMS.	01-01
KY	597	I2759519	M23	08-99
KY	597	I2774437	M23	11-99
KY	597	A2636516	M9	01-01
KY	597	A2660395	M9, M23	08-01
KY	597	A2624009	M9	10-00
KY	597	A2624009	WONT CYCLE OR EJECT.	10-00
KY	597	A2660395	M23	08-01
KY	597	I2785268	EJECTOR MISSING EXTRACTOR, SPRING, AND	03-00
KY	597	I2784399	PLUNGER	03-00
KY	597	I2935214M	WILL NOT EJECT	06-99
LA	597	I2783702	M23	03-00
LA	597	A2628974	M9, M23	11-00
LA	597	I2917347M	M9, M10, M23	10-98
LA	597	I2722415	M5, M10	11-98
LA	597	I2765947	M9	09-99
LA	597	I2684822	WOULD NOT EXTRACT.	04-98
LA	597	I294372M	M10	
LA	597	I2918897	CLIP CRACKED.	
LA	597	I2920736M	BREECH BOLT BROKEN.	11-98
LA	597	I2943729M	HANGS, EJECTOR BENT.	10-99
LA	597	I2783688	M23 BALL WON'T RETAIN EXTRACTOR,	03-00
MD	597	I2630954	MOUTH OF CHAMBER DAMAGED FROM	08-97
MD	597	I2675633	WON'T FIRE. FIRE ONCE WITHOUT DETONATOR	02-98
MI	597	I2751188	CLOSED.	05-99
MI	597	A26832898	JAMS.	12-00
MI	597	I2777268	CLIP DOESN'T HOLD. GUN WILL ONLY GROUP FROM 11/2"	01-00
MI	597	A2662264	TO 2" AT 25 YDS.	08-01
MI	597	I2943634M	HANDLE FOR BOLT FALLS OUT.	10-99
MI	597	I2770376	M23, M33	10-99