

INSTALLED NEW STYLE EJECTOR & REPLACED MAG AND TEST FIRED.	21072	\$26.70	5	150004
INSTALLED NEW STYLE EJECTOR AND TEST FIRED.	21072	\$18.00	1	150010
INSTALLED NEW EJECTOR AND TEST FIRED.	21072	\$26.23	7	150018
INSTALLED NEW STYLE EJECTOR AND TEST FIRED.	21072	\$21.23	1	150019
REFIT MAG CATCHER, REPLACED MAGAZINE BOX ASSY.	20309	\$45.50	4	148203
REPAIRD MAG LATCH ASSY AND TESTED.	20309	\$21.50	55	148202
REPLACED EJECTOR WITH NEW STYLE, CLEANED ACTION AND TEST FIRED.	21072	\$38.73	13	124057
INSTALLED NEW STYLE EJECTOR, REPLACED MAGAZINE AND TEST FIRED.	21072	\$22.23	1	150068
REPLACED EJECTOR AND TEST FIRED.	21072	\$21.23	9	150060
REPLACED EJECTOR AND BOLT ASSY AND TEST FIRED.	21072	\$89.84	2	150054
CUSTOMER STATES STIFFER DAMP AFTER TESTING FIRED NEW EJECTOR & MAG. TEST FIRED AND ALL TESTED	21072	\$18.00	1	150070
NEW STYLE EJECTOR, TEST FIRED.	21072	\$23.73	3	157757
REPLACED EXTRACTOR, SPRING AND PLUNGER	21072	\$41.80	4	157760
REPLACED EXTRACTOR AND PLUNGER. TEST FIRED.	21072	\$40.20	20	157761
CLEANED, TEST FIRED AND REPLACED MAGAZINE.	20204	\$26.25	27	131707
CLEANED & POLISHED CHAMBER, ADJUSTED EJECTOR	20204	\$26.25	15	131717
REPLACED EXTRACTOR, SPRING & PLUNGER.	20204	\$40.65	0	131721
REPLACED MAGAZINE AND CLEANED	20204	\$40.65	0	131721
REPLACED EXTRACTOR, PLUNGER, RET SPRING & RIVET.	107416	\$32.92	108	134638
ADJUSTED EXTRACTOR, INCREASED TENSION ON EXTRACTOR SPRING, CLEANED CHAMBER.	107416	\$36.00	17	134646
REPLACED EXTRACTOR, PLUNGER & SPRING AND TESTED.	21049	\$19.30	10	91930
INSTALLED LONGER EXTRACTOR	21025	\$24.09	15	138961
REPLACED MAG BOX ASSY AND TESTED	21025	\$24.27	6	138972
REPLACED BOLT ASSY MAG.	21025	\$105.91	47	138971
REPLACED EJECTOR.	21025	\$21.91	67	138966
CLEANED, TESTED, AND POLISHED. REPLACED MAGAZINE.	107416	\$40.50	1	134686
RETURNED TO FACTORY	20021	\$10.00	5	83882
REASSEMBLED & STAKED TRIGGER LINK.	20021	\$10.00	13	83875
REPLACED EJECTOR, EXTRACTOR PLUNGER AND SPRING.	21031	\$41.29	10	77153
CLEANED, POLISHED CHAMBER AND TESTED.	21030	\$34.90	1	104239
REPLACED PIN AND SPRING ASSY IN REC.	21030	\$20.00	1	104241
CLEANED, REASSEMBLED, TESTED, RETURNED TO FACTORY.	21030	\$38.80	1	104242
REPLACED BOLT.	21030	\$109.81	30	104244
FIT MAG LATCH TO GIVE MORE POSITIVE CATCH.	20108	\$48.60	1	132111