

INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$29.58	2	143818
INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$29.58	3	142874
INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$29.58	1	142863
ADJUSTED MAG LATCH, SAFETY & TEST FIRED.	21047	\$27.72	5	142900
INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$29.58	3	142885
REPLACED APERTURE & SCREW, REINSTALLED MAG LATCH, INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$47.09	7	142883
INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$29.58	3	142886
SENT TO FACTORY FOR REPAIRS.	21047	\$20.96	2	143822
ADJUSTED MAGAZINE LATCH, SAFETY & TEST FIRED.	21047	\$27.35	4	144423
REPLACED TRIGGER HOUSING ASST, SAFETY & TEST FIRED.	21047	\$71.58	2	142903
REINSTALLED OPERATING HANDLE CORRECTLY.				
INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$30.25	1	144428
SENT TO FACTORY.	21047	\$31.45	10	144427
INSTALLED NEW STYLE EJECTOR, ADJUSTED MAGAZINE LATCH, SAFETY & TEST FIRED.	21047	\$29.95	1	144424
TIGHTENED REAR SIGHT BASE, SAFETY & TEST FIRED.	21047	\$27.72	3	144422
REPLACED TRIGGER HOUSING ASST, SAFETY & TEST FIRED.	21047	\$66.58	4	144421
REALIGNED & TIGHTENED REAR SIGHT, DONE TO SPEC OK, SAFETY & TEST FIRED.	21047	\$32.35	2	144420
ADJUSTED MAGAZINE LATCH, INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$34.46	3	142912
INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$34.95	3	142911
TIGHTENED FRONT REAR SIGHT, ADJUSTED MAGAZINE LATCH, SAFETY & TEST FIRED.	21047	\$27.72	2	142910
INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$29.58	1	142908
INSTALLED NEW STYLE EJECTOR, TIGHTENED REAR SIGHT, SAFETY & TEST FIRED.	21047	\$29.95	1	142905
TIGHTENED REAR SIGHT, INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$34.58	1	144425
REPLACED BOLT SPRING ROVET, BOLT HEAD SPRING, INSTALLED NEW STYLE EJECTOR, SAFETY AND TEST FIRED.	21047	\$40.15	6	143904
INSTALLED NEW STYLE EJECTOR, SAFETY AND TEST FIRED OK.	21047	\$37.75	4	143903
RELIEVED BINDING ON EJECTOR, ADJUSTED MAGAZINE LATCH, SAFETY, TEST FIRED.	21047	\$32.08	7	143845
ADJUSTED MAGAZINE LATCH, SAFETY AND TEST FIRED.	21047	\$29.85	2	143885
REPLACED TRIGGER HOUSING ROCKET SAFETY AND TEST FIRED OK.	21047	\$30.52	6	143899
INSTALLED NEW STYLE EJECTOR, SAFETY AND TEST FIRED.	21047	\$69.75	2	143884
REPLACED BOX MAGAZINE, SAFETY AND TEST FIRED.	21047	\$31.96	4	143843
INSTALLED NEW STYLE EJECTOR, SAFETY AND TEST FIRED.	21047	\$39.00	3	143886
ADJUSTED MAGAZINE LATCH, SAFETY AND TEST FIRED.	21047	\$36.96	3	143891
FIRED WITH SEVERAL MAGAZINES OF REM AMMO.	21047	\$37.85	3	143897
INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$32.08	3	143874