

REPLACED EXTRACTOR, SPRING AND PLUNGER.	20960	\$51.11	1	25283
REPLACED EXTRACTOR, SPRING AND PLUNGER.	20960	\$50.11	1	25282
REPLACED MAG BOX ASSY.	21090	\$6.70	1	115903
INSTALLED NEW EJECTOR.	21090	\$30.17	23	115908
INSTALLED NEW EJECTOR AND FUNCTION FIRED.	21090	\$52.23	2	115923
REPLACED MAGAZINE & EJECTOR, POLISHED & DEBURRED CHAMBER & BOLT.	20803	\$116.71	30	112956
ADJUSTED CLIP CATCH AND TEST FIRED.	20902	\$16.00	48	113874
INSTALLED NEW STYLE EJECTOR AND TEST FIRED	21027	\$36.32	6	149407
REINSTALLED PIN THAT HOLDS TRIGGER ASSY TO SEAR AND REINSTALLED SEAR SPRING.	20616	\$35.00	23	153626
TEST FIRED WITH NO PROBLEMS, SENT TO MAIN & SON SPTG. GDS.	20616	\$19.01	16	153607
REPLACED OLD EJECTOR AND MAGAZINE LATCH.	20616	\$16.59	62	153123
REPLACED EJECTOR.	20616	\$15.17	1	153082
CHECKED OVER ACTION, OILED, TEST FIRED, REPLACED MAGAZINE.	21024	\$25.79	19	70575
REPLACED MAG ASSY.	21024	\$25.79	19	70576
REPLACED WITH NEW MODEL EJECTOR AND TEST FIRED.	21039	\$19.00	11	116554