

RD-542-1 Rev. 2-15-61

Custom Complaint

P.I. No GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL
GENERAL CONDITION: Good R #: 25226
OUTSIDE WORK: No DATE: 12-8-71
FIRED AMMO TYPE: _____ FROM: QUEEN CITY DIST. CO.
& CONDITION: _____ ALBUQUERQUE, NM.
PROOF: REP-M INSP.: 9 TEST: 87 GUN #: 6448107
HEADING: O.K. CODE: PU- 6/71
BREECH OPENING: - G&C/CAL.: 3006 S&C.
RECOIL SHOULDERS: O.K. CHECKED BY: C. PROSSER
CHAMBER: O.K. APPROVED: _____
TEST: No APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

CORNER OF TRIGGER CONNECTOR DAMAGED. CONNECTOR-
SEAR ENGAGEMENT .005.

COMPLAINT: "FIRES UPON CLOSING ACTION"

INCIDENT: FOLLOWS DOWN.

PLAINTIFF'S
EXHIBIT

3266

COMMENTS: TRIGGER CONNECTOR-SEAR ENGAGEMENT SET TOO
CLOSE. THE CONNECTOR CORNER BUSH DOWN SO THAT IT
BECAME IMPOSSIBLE FOR THE ACTION TO STAY COCKED.

1 of 1

AL 0029798