

KY	710	71004781	01-01	BROKEN BOLT STOP.	UPDATED.	21072	\$14.00	1 157597
KY	710	71001380	01-01	FIRING PIN ASSY BROKEN.	REPLACED FIRING PIN ASSY.	21072	\$14.00	1 157659
KY	710	71002575	01-01	BOLT STOP BROKEN.	REPLACED BOLT STOP.	21072	\$14.00	5 124096
KY	710	71003645	01-01	M5	REPLACED BOLT STOP & BOLT HEAD.	21072	\$14.00	5 124094
KY	710	71003066	01-01		REPLACED STOCK. UPDATED.	21072	\$17.50	8 150041
KY	710	71003825	01-01	STIFF ACTION.	REPLACED BOLT BOYD FOR SMOOTHER ACTION.	21072	\$14.00	1 124047
KY	710	71005074	01-01	M5		21072	\$17.50	11 150592
KY	710	71002811	01-01		MAG LATCH.	21072	\$14.00	7 157556
KY	710	71003888	01-01	BROKEN MAG LATCH.		21072	\$14.00	4 157557
WI	710	71004661	01-01	BOLT COMES OUT WHEN PULLED TO REAR.	SENT TO PADUCAH FOR REPAIR.	21039	\$32.00	1 116545
KY	710	71006397	02-01	BOLT VERY HARD.	UPDATED.	21072	\$14.00	12 150666
KY	710	71007102	02-01	M5	UPDATED.	21072	\$14.00	5 150672
KY	710	71004269	02-01	M5	UPDATED.	21072	\$14.00	5 150670
KY	710	71006002	02-01		RECEIVER INSERT, STOCK.	21072	\$14.00	4 150663
KY	710	71001220	02-01	M5	UPDATED.	21072	\$14.00	2 150638
OK	710	71004269	02-01	BOLT HANDLE & HEAD BROKE OFF.	SENT TO PADUCAH FOR REPAIRS.	21047	\$25.07	1 143710
OH	710	71006860	02-01	LOCK FOR BOLT BROKEN.	SENT TO PADUCAH SHOOTERS SUPPLY.	21060	\$23.75	0 SH4568
KY	710	71006551	02-01	BOLT HEAD STUCK IN BBL, MISSING FIRING PIN ASSY & BOLT ASSY PIN.	REPLACED FIRING PIN ASSY & BOLT ASSY PIN.	21072	\$14.00	7 124017
KY	710	71007402	02-01	FIRING PIN WILL NOT STAY LOCKED IN BOLT.	REPLACED BOLT BODY.	21072	\$14.00	8 124013

Subject to Protective Order - Williams v. Remington

BARBER - REM DOCSB0010180

MAE00010096