

KY	710	71009943	03-01	M8	CHANGED EXT.	21072	\$14.00	1 150654
KY	710	71010721	03-01	NO NOTE ENCLOSED.	TESTED FUNCTION & SAFETY, ALL TESTED OK.	21072	\$14.00	6 150473
KY	710	71008631	03-01	NO NOTE ENCLOSED, BAD BOLT STOP.	UPDATED.	21072	\$14.00	7 150486
KY	710	71009599	03-01	MAG LATCH BROKEN.	REPLACED MAG LATCH.	21072	\$14.00	7 150483
KY	710	71002843	03-01	M5	REPLACED BOLT HANDLE.	21072	\$14.00	1 150726
KY	710	71009242	03-01		REPLACED STOCK & BOLT STOP CLIP.	21072	\$14.00	7 150525
KY	710	71010333	03-01		ADJUSTED EXTRACTOR.	21072	\$14.00	7 150512
KY	710	71010326	03-01		REPLACED BOLT HEAD.	21072	\$14.00	7 150505
KY	710	71008904	03-01		REPLACED MAGAZINE AND TESTED.	21072	\$14.00	7 150500
KY	710	71009033	03-01	BOLT STOP.	BOLT STOP.	21072	\$18.00	10 150546
KY	710	71009360	03-01	TRIGGER GUARD BROKEN, TRIGGER BENT.	REPLACED TRIGGER & GUARD.	21072	\$14.00	1 150578
KY	710	71010362	03-01	M5	UPDATED.	21072	\$14.00	3 150563
KY	710	71007709	03-01	SCREW WOULD NOT HOLD SCOPE BASE TIGHT.	REPLACED FACTORY SCREWS WITH LONGER WEAVER	21072	\$14.00	5 150740
MS	710	71008025	03-01	WHSE INSPECTION.	WHSE INSPECTION.	107773	\$15.00	1 DK1244
MS	710	71008245	03-01	WHSE INSPECTION.	WHSE INSPECTION.	107773	\$15.00	1 DK1245
MS	710	71009128	03-01	WHSE INSPECTION.	WHSE INSPECTION.	107773	\$15.00	1 DK1246
MS	710	71010275	03-01	WHSE INSPECTION.	WHSE INSPECTION.	107773	\$15.00	1 DK1247
MS	710	71010313	03-01	WHSE INSPECTION.	WHSE INSPECTION.	107773	\$15.00	1 DK1248
WI	710	71008564	03-01	M5	MAILED TO PADUCAH FOR WARRANTY.	20616	\$19.61	9 153028

Subject to Protective Order - Williams v. Remington

BARBER - REM DOCSB0010183

MAE00010099