

KY	710	71012988	04-01	FIRING PIN ASSY BROKEN.	REPLACED FIRING PIN ASSY.	21072	\$14.00	5 157551
KY	710	71011605	04-01	BOLT HEAD INSTALLED IN WRONG POSITION.	BOLT HEAD INSTALLED IN WRONG POSITION.	21072	\$14.00	5 157553
KY	710	71012991	04-01	BOLT BODY WILL NOT HOLD FIRING PIN ASSY.	REPLACED BOLT BODY.	21072	\$14.00	1 157651
KY	710	71013984	04-01	M5		21072	\$14.00	11 124060
KY	710	71011049	04-01	BOLT WILL NOT OPEN, RIGHT BACKER HAD SLIPPED PAST REC		21072	\$14.00	1 150458
KY	710	71011081	04-01	MAG LATCH.		21072	\$14.00	9 150475
KY	710	71011499	04-01	TRIGGER & GUARD BROKEN		21072	\$14.00	2 124079
KY	710	71013397	04-01	M1	REPLACED SCOPE, CROSSHAIRS BROKEN AND	21072	\$30.75	5 124070
KY	710	71011161	04-01	M23	REPLACED BOLT HEAD & BOLT BODY AND TESTED.	21072	\$14.00	32 150587
KY	710	71011100	04-01	M8		21072	\$14.00	22 150589
KY	710	71013890	04-01	HARD TO CHAMBER ROUND.		21072	\$14.00	4 150599
KY	710	71011494	04-01	REC INSERT BROKE A REAR BOLT		21072	\$14.00	7 157558
KY	710	71011502	04-01	STIFF BOLT.	REMOVED BURR FROM BOLT HEAD, INSTALLED NEW BOLT	21072	\$14.00	7 157560
KY	710	71013048	04-01		REPLACED SCOPE.	21072	\$14.00	3 157574
KY	710	71013214	04-01	BOLT HANDLE FELL OFF.		21072	\$14.00	3 157575
MS	710	71011275	04-01	WAREHOUSE INSPECTION.	WAREHOUSE INSPECTION.	107773	\$15.00	1 DK1479
CO	710	71012526	04-01	BOLT RELEASE BROKEN & FIRED BRASS INDENTED.	RETURNED TO FACTORY.	106412	\$15.00	4 122435
KY	710	71015547	05-01	UPDATE.	UPDATED.	21072	\$14.00	3 150620
KY	710	71014466	05-01	SAFETY ON BOLT BROKEN.	UPDATED.	21072	\$14.00	12 150667

Subject to Protective Order - Williams v. Remington

BARBER - REM DOCSB0010187

MAE00010103