

CT	710	71014340	05-01		FORWARDED TO PADUCAH SHOOTERS SUPPLY.	20629	\$15.00	1 151098
CT	710	71013252	05-01		FORWARDED TO PADUCAH SHOOTERS SUPPLY.	20629	\$10.25	5 151088
KY	710	71013252	05-01	WON'T FIRE.	TEST FIRED, ALL OK.	21072	\$16.25	5 124014
KY	710	71014349	05-01	MAG LATCH BROKEN.	UPDATED AND NEW STOCK.	21072	\$14.00	4 124010
KY	710	71015570	05-01	M5	REPLACED BOLT HANDLE.	21072	\$14.00	5 150746
KY	710	71017939	05-01	M5	UPDATED.	21072	\$14.00	4 150470
KY	710	71014187	05-01	BOLT STOP.	BOLT STOP	21072	\$14.00	1 150727
KY	710	71018076	05-01	MAG LATCH BROKEN.	REPLACED MAG LATCH.	21072	\$14.00	1 150714
KY	710	71014429	05-01	MAG LATCH BROKEN.	REPLACED STOCK.	21072	\$14.00	7 150507
KY	710	71015522	05-01		REPLACED REC INSERT ASSY.	21072	\$14.00	7 150501
KY	710	71014979	05-01	BOLT HARD TO OPEN AND CLOSE.	REPLACED BOLT.	21072	\$14.00	3 150568
KY	710	71017209	05-01	BROKEN MAG LATCH.	REPLACED MAG LATCH.	21072	\$14.00	3 150562
OH	710	71016931	05-01	SCOPE RING RUBBER FELL OUT.	RETURNED TO PADUCAH.	21080	\$24.50	100 SH4557
MS	710	71017674	05-01	WHSE INSPECTION.	WHSE INSPECTION.	107773	\$15.00	1 DK1249
MN	710	71015718	05-01	BROKEN TRIGGER GUARD.	SENT TO PADUCAH.	20017	\$33.50	2 149653
MN	710	71017209	05-01	CLIP LATCH.	SENT TO PADUCAH.	20017	\$33.74	12 149618
MN	710	71017423	05-01	BOLT WON'T GO IN.	SENT TO PADUCAH.	20017	\$33.50	8 149615
CT	710	71014345	05-01	FORWARD TO PADUCAH.	FORWARDED TO PADUCAH.	20629	\$10.82	11 151155
KY	710	71016403	05-01	ACTION STIFF, BACKER OUT OF PLACE.	BACKER OUT OF PLACE.	21072	\$14.00	1 157600

Subject to Protective Order - Williams v. Remington