

KY	710	71027703	08-01	BOLT STOP.	REPLACED BOLT STOP.	21072	\$14.00	4 150458
KY	710	71025923	08-01	TRIGGER GUARD BROKEN.	REPLACED TRIGGER GUARD.	21072	\$14.00	4 150754
KY	710	71027101	08-01	BOLT STOP	REPLACED BOLT STOP.	21072	\$14.00	2 150463
KY	710	71025676	08-01	STOCK WOULD NOT HOLD BOLT STOP	UPDATED.	21072	\$14.00	7 150643
KY	710	71028323	08-01	TRIGGER & GUARD BROKEN.	REPLACED TRIGGER & GUARD.	21072	\$14.00	3 150733
KY	710	71028452	08-01	CHECK OUT.	CHECKED OUT AND TESTED.	21072	\$14.00	1 150724
KY	710	71027691	08-01	FIRING PIN ASSY WOULD NOT STAY IN BOLT.	REPLACED BOLT BODY AND TESTED.	21072	\$14.00	7 150528
KY	710	71027429	08-01	BOLT WAS UNCOCKED.	COCKED BOLT AND TESTED.	21072	\$14.00	7 150521
KY	710	71026252	08-01		REPLACED STOCK.	21072	\$14.00	7 150510
KY	710	71025670	08-01	FIRED WHEN CLOSED BOLT ON LIVE ROUND.	REPLACED REC INSERT ASSY.	21072	\$14.00	7 150509
KY	710	71027347	08-01	BAD BOLT STOP.	REPLACED BOLT STOP.	21072	\$14.00	1 150577
KY	710	71027371	08-01	WON'T FEED.	TESTED. ALL FEED FINE.	21072	\$14.00	1 150576
OH	710	71025530	08-01	BOLT WHEN IN LOCK POSITION, DOES NOT LOCK.	CHECKED FUNCTION ALL OK. RETURNED TO FACTORY FOR REPAIR, RETURNED TO	21080	\$44.50	10 SH4818
AL	710	71028813	08-01	RETURNED TO PADUCAH.	RETURNED TO PADUCAH.	21056	\$8.50	1 136733
OR	710	71028739	08-01	CHECK FOR MALFUNCTION.	SHIPPED TO PADUCAH.	20023	\$30.27	1 110570
CT	710	71028483	08-01	FORWARD TO PADUCAH.	FORWARDED TO PADUCAH.	20629	\$10.82	1 151123
CT	710	71026251	08-01	FORWARD TO PADUCAH.	FORWARDED TO PADUCAH.	20629	\$10.82	4 151140
CT	710	71025630	08-01	FORWARD TO PADUCAH.	FORWARDED TO PADUCAH.	20629	\$10.82	13 151164
CT	710	71026590	08-01	FORWARD TO PADUCAH.	FORWARDED TO PADUCAH.	20629	\$10.82	1 151191

Subject to Protective Order - Williams v. Remington

BARBER - REM DOCSB0010195

MAE00010111