

OK	597	2758918	08-99	M9	INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$34.58
KY	597	2759519	08-99	M23	REFIT MAG CATCHER, REPLACED MAGAZINE BOX ASSY.	20309	\$45.50
CT	597	2758124	08-99	M9, M10, M23, M29	REPLACED EJECTOR, EXTRACTOR, PLUNGER & SPRING, CHECKED OVER.	20629	\$47.78
IL	597	2758285	08-99	M24, M31	REPLACED EJECTOR, REMOVED BURRS AT CHAMBER AREA AND TEST FIRED.	21028	\$29.88
LA	597	2765947	09-99	M9	ADJUSTED EXTRACTOR, INCREASED TENSION ON EXTRACTOR SPRING, CLEANED	107416	\$36.00
OR	597	2786716	09-99	M9	FITTED EXTRACTOR HOOK, BENT EJECTOR UP & RIGHT, UNDERCUT RIGHT SIDE OF	21043	\$21.00
AL	597	2764606	09-99	M10	REPLACED EXTRACTOR SPRING, STRIPPED & EXAMINED, REFIT FRONT LINK	21056	\$24.10
NV	597	2943513M	09-99	WILL NOT FIRE.	OF TRIGGER PIN AND TESTED.	80023	\$16.00
MI	597	2770376	10-99	M23, M33	FIT MAG LATCH TO GIVE MORE POSITIVE CATCH.	20108	\$48.60
OH	597	2771848	10-99	SHELL GOT JAMMED IN CHAMBER, SCOPE MOUNT HOLE STRIPPED	INSTALLED EXTRACTOR, PLUNGER & SPRING AND MAG BOX ASSY, CLEANED, CHECKED	21060	\$61.56
MN	597	2944468M	10-99	OUT.	REDRILLED & TAPPED RECEIVER & REM BBL TO ACCEPT 8-40 SCREWS AND SUPPLIED	20017	\$50.64
OK	597	2768668	10-99	M9	REINSTALLED BOLT HANDLE & INSTALLED NEW STYLE EJECTOR, SAFETY & TEST	21047	\$34.46
TX	597	2770815	10-99	MAGAZINE WILL NOT STAY IN RIFLE.	REINSTALLED MAG CATCH SPRING & PIN, CHECKED OVER.	21017	\$17.50
TN	597	2944119M	10-99	BOLT HANDLE WILL NOT STAY IN BOLT.	REPAIRED LOOSE BOLT HANDLE RETAINER & MADE & FIT NEW RETAINER RIVET AND	21052	\$20.60
MI	597	2943634M	10-99	HANDLE FOR BOLT FALLS OUT.	REPLACED BOLT.	21030	\$109.81
MI	597	2768457	10-99	M10	REPLACED BROKEN EJECTOR AND TESTED, REPLACED EJECTOR & MAGAZINE LATCH	20108	\$42.16
IL	597	2770148	10-99		AND TEST FIRED.	21028	\$35.49
CT	597	2775073	11-99	M9, M23	CHECKED OVER, CLEANED & OILED, SAFETY & FUNCTION TESTED, INSTALLED EJECTOR.	20629	\$41.95
OR	597	2775518	11-99	BROKEN SAFETY.	INSTALLED NEW EJECTOR, CHECKED SAFETY.	20023	\$37.93

Subject to Protective Order - Williams v. Remington

BARBER - REM DOCSB0010248

MAE00010164