

AL	597	A2633053	12-00	M9	REPLACED EJECTOR AND TEST FIRED.	21026	\$33.65
NY	597	A2632585	12-00	M137	REPLACED EJECTOR, SAFETY & FUNCTION CHECKED AND TESTED.	21177	\$20.00
OK	597	A2632360	12-00	M9	REPLACED EJECTOR.	21047	\$18.73
AL	597	A2633408	01-01	JAMS	ADJUSTED EJECTOR.	21056	\$22.50
AL	597	A2633688	01-01	JAMS	ADJUSTED EJECTOR.	21056	\$22.00
AL	597	A2633425	01-01	JAMS.	ADJUSTED EJECTOR.	21056	\$22.50
OR	597	A2633564	01-01	ACTION WON'T LOCK OPEN. CLIP WON'T LOCK IN WITH AMMO	ADJUSTED HOLD OPEN LATCH.	20023	\$29.55
CAN	597	A2637475	01-01	M18	CHAMBER STOCK. CLEANED & OILED BBL, CHAMBER,	268418	\$18.65
MI	597	A2636387	01-01	M9, M10	REPLACED EJECTOR AND TEST FIRED.	20108	\$46.17
NY	597	A2636817	01-01	M201	CLEANED DEBRIS FROM BOLT FACE, REPLACED EJECTOR, SAFETY & FUNCTION	21177	\$20.00
NC	597	A2633694	01-01	M5	DRILLED OUT BOLT HANDLE & RIVET AND INSTALLED NEW ONE.	21192	\$23.20
CAN	597	A2636350	01-01	M9, M23	EXCHANGED MAGAZINE, EJECTOR & FIRING AND TESTED.	268418	\$45.23
CAN	597	A2635387	01-01	M9, M10	FIT NEW EJECTOR & EXTRACTOR AND TESTED.	268418	\$13.82
SD	597	A2633534	01-01		FUNCTIONS & SAFETY CHECKED, TEST FIRED.	20510	\$25.80
SD	597	A2637899	01-01	M9	FUNCTIONS & SAFETY CHECKED, TEST FIRED. ADJUSTED EXTRACTOR.	20510	\$30.70
SD	597	A2633606	01-01	M9	FUNCTIONS & SAFETY CHECKED, TEST FIRED. ADJUSTED EXTRACTOR.	20510	\$30.80
SD	597	A2637899	01-01	M9	FUNCTIONS & SAFETY CHECKED, TEST FIRED. NO MALFUNCTIONS.	20510	\$27.80
OH	597	A2632231	01-01	REPEATEDLY JAMS UP.	GROUND EJECTOR, REPLACED CLIP & INSTALLED NEW EJECTOR PIN, CLEANED,	21060	\$59.18
OH	597	A2633609	01-01	JAMS SHELLS.	GROUND SIDE OF EJECTOR, CLEANED, CHECKED AND TEST FIRED.	21060	\$45.75

Subject to Protective Order - Williams v. Remington

BARBER - REM DOCB0010258

MAE00010174