

Subject to Protective Order - Williams v. Remington

IL	597	A2641210	02-01	M29, M33	REPLACED EJECTOR & MAG BOX AND TEST FIRED.	21028	\$49.70
NY	597	A2636346	02-01	M138	REPLACED EJECTOR, ADJUSTED ACTION TIGHTNESS, SAFETY & FUNCTION CHECKED	21177	\$20.00
NY	597	A2637458	02-01	M138	REPLACED EJECTOR, SAFETY & FUNCTION CHECKED AND TEST FIRED.	21177	\$20.00
NY	597	A2639165	02-01	M137	REPLACED EJECTOR, SAFETY & FUNCTION CHECKED AND TESTED.	21177	\$20.00
NY	597	A2638027	02-01	M9	REPLACED EJECTOR, SAFETY & FUNCTION CHECKED AND TESTED.	21177	\$20.00
CT	597	A2638277	02-01	M9, M10, M20, M23	REPLACED EXTRACTOR, SPRING & PLUNGER, REAR SIGHT ASSY & BASE, REPLACED MAG ASSY, CHECKED EXTRACTOR AND TEST FIRED.	20629	\$72.50
NC	597	A2640797	02-01	M23	STRIPPED DOWN, EXCHANGED EJECTOR, REBUILT AND TESTED.	21102	\$40.78
CAN	597	A2636336	02-01	M9	ADJUSTED ACTION TIGHTNESS, REPLACED EJECTOR, SAFETY & FUNCTION CHECKED	268418	\$13.03
NY	597	A2645276	03-01	M137	ADJUSTED TRIGGER LINKAGE, REPLACED EJECTOR, SAFETY & FUNCTION CHECKED	21177	\$20.00
NY	597	A2644003	03-01	M110		21177	\$20.00
OH	597	A2643701	03-01	DIDN'T WANT.	CLEANED, CHECKED AND TEST FIRED.	21060	\$30.75
OK	597	A2645020	03-01	M9	INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$29.95
OH	597	A2644284	03-01	CHECK OVER AND RETURN.	INSTALLED NEW TYPE EJECTOR, GROUND EJECTOR FOR BOLT CLEARANCE, CLEANED, REMOVED BURR FROM REAR OF CHAMBER, REPLACED EJECTOR, SAFETY & FUNCTION	21060	\$52.48
NY	597	A2645466	03-01	M110	REMOVED BURRS AT CHAMBER AREA AND TEST FIRED.	21177	\$20.00
IL	597	A2644347	03-01	M24	REPLACED BOLT SPRING & RIVET, SAFETY & FUNCTION CHECKED AND TESTED.	21028	\$22.00
NY	597	A2644196	03-01	M145	REPLACED EJECTOR, SAFETY & FUNCTION CHECKED AND TEST FIRED. ADJUSTED	21177	\$20.00
NY	597	A2643816	03-01	M138	REPLACED MAG BOX ASSY, REINSTALLED EXTRACTOR, INSTALLED NEW STYLE	21047	\$41.36
OK	597	A2644383	03-01		ADJUSTED ACTION TIGHTNESS, REPLACED EJECTOR, SAFETY & FUNCTION CHECKED	21177	\$20.00
NY	597	A2645909	04-01	M23			