

OH	597	A2650138	05-01	NOTHING ON PAPERWORK.	REPLACED TRIGGER ASSY, CLEANED, CHECKED AND TEST FIRED.	21060	\$99.48
OH	597	A2650160	06-01	TO BE CHECKED.	REPLACED TRIGGER HOUSING, CLEANED, CHECKED AND TEST FIRED.	21060	\$76.48
CO	597	A2652149	05-01	M9 MAGAZINE NOT STAYING IN RIFLE.	RETURNED TO FACTORY, THEN SENT BACK TO CUSTOMER.	106412	\$30.00
OR	597	A2650219	05-01	BULLETS NOT LOADING INTO RIFLE.	UPDATED EJECTOR, REFIT MAG LATCH. BEAD BLASTED BBL & BLUED, CLEANED.	20023	\$43.82
OH	597	A2656739	06-01	RUSTED BBL.	CHECKED AND TEST FIRED.	21060	\$81.75
CT	597	A2655898	06-01	M25	CHECKED OVER, CLEANED & OILED, SAFETY & FUNCTION TESTED.	20629	\$40.75
CT	597	A2655856	06-01	M9, M10, M23, M33	CLEANED, OILED AND POLISHED CHAMBER, CHECKED OVER, SAFETY & FUNCTION	20629	\$50.03
OR	597	A2656025	06-01	JAMMING.	CLEANED, REPLACED EJECTOR AND TESTED.	20023	\$46.24
SD	597	A2653350	06-01	MISFIRES.	FUNCTIONS & SAFETY CHECKED, TEST FIRED, REPLACED MAGAZINE.	20510	\$32.47
AL	597	A2655731	06-01	M10	HONED CHAMBER.	21056	\$22.50
OK	597	A2657258	06-01	M9	INSTALLED NEW STYLE EJECTOR. DEBURRED MAGAZINE LATCH, SAFETY &	21047	\$29.58
OK	597	A2657306	06-01	M9	INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$29.95
OK	597	A2655923	06-01	M9	INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$29.58
OK	597	A2654289	06-01	M9	INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$29.95
OK	597	A2657036	06-01	M9	INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$18.73
OH	597	A2657270	06-01	BLEW UP ON CUSTOMER.	INSTALLED NEW TYPE EJECTOR, CLEANED, CHECKED AND TEST FIRED.	21060	\$42.98
OH	597	A2656014	06-01	HANGING SHELLS	INSTALLED NEW TYPE OF EJECTOR, CLEANED, CHECKED AND TEST FIRED.	21060	\$48.48
OK	597	A2654311	06-01	M23	REPLACED BOLT SPRING & RIVET, SAFETY & TEST FIRED.	21047	\$30.91
MI	597	A2653643	06-01	M9	REPLACED EJECTOR, POLISHED CHAMBER AND TEST FIRED.	20108	\$65.97