

REINSTALLED FIRING PIN ASSY AND TESTED BOLT, SAFETIES & FUNCTIONS.	21072	\$19.02	1	142238
REPLACED FIRING PIN ASSY & OLD BOLT BODY.	21072	\$17.72	1	142058
INSTALLED NEW BACKERS.	21072	\$19.02	4	135635
CHECKED UPDATE, ALL OK.	21072	\$19.47	1	142210
CHECKED UPDATE, ALL OK.	21072	\$19.02	2	142214
CHECKED UPDATE, ALL OK.	21072	\$19.02	2	142215
RIFLE HAS ALREADY BEEN UPDATED, CHECKED UPDATE. ALL OK.	21072	\$19.02	1	141914
REPLACED REC. INSERT ASSY, TESTED FINE.	21072	\$19.02	1	142070
REPLACED REC. INSERT ASSY.	21072	\$21.04	1	142076
TESTED FINE, UPDATED ALREADY.	21072	\$20.09	7	135923
UPDATED AT FACTORY, SEEMED TO WORK FINE.	21072	\$19.47	1	142051
TALKED WITH TODD PIERSON AT REMINGTON, RIFLE TESTED OK.	21072	\$19.02	7	136593
RESTALLER BACKERS.	21072	\$20.00	1	139986
RESTALLER BACKERS.	21072	\$20.00	2	139985