

RETURNED TO REMINGTON FOR REPAIRS.	21047	\$21.45	12	132230
CHECKED UPDATE, ALL SEEMS OK.	21072	\$19.02	2	142088
CHECKED UPDATE, ALL SEEMS OK.	21072	\$19.02	2	142089
INSTALLED RIGHT BACKER CORRECTLY.	21072	\$21.04	1	135922
REPLACED TRIGGER ASSY, INSTALLED ACTION SHIMS.	21072	\$20.00	3	139968
INSTALLED BACKERS AND REC. INSERT ASS.	21072	\$20.00	1	139981
UPDATE CHECKED OK. REPLACED REV. INSERT ASSY.	21072	\$19.02	1	142232
REPLACED SCOPE.	21072	\$19.02	1	135652
REMOUNTED & BORESIGHTED SCOPE.	20616	\$14.00	1	111229
STRAIGHTENED SCOPE, REPLACED BOLT BODY, INSTALLED LEFT & RIGHT BACKERS.	21072	\$19.00	3	136318
REPLACED SCOPE & BORESIGHTED.	21072	\$18.58	1	142097
REPLACED BOLT BODY, INSTALLED LEFT BACKER & RIGHT BACKER.	21072	\$21.04	1	136328
REPLACED BOLT BODY, INSTALLED LEFT BACKER & RIGHT BACKER.	21072	\$19.00	1	136329
REPLACED BOLT BODY, INSTALLED LEFT & RIGHT BACKERS.	21072	\$19.00	1	136330