

SHIPPED TO PADUCAH SHOOTERS FOR EVALUATION.	20616	\$23.02	15	137982
RETURNED TO PADUCAH FOR REPAIRS.	21047	\$30.44	13	132249
REPLACED REC. INSERT ASSY, UPDATE CHECKED OK.	21072	\$19.02	1	142279
REPLACED STOCK & REC. INSERT.	21072	\$19.02	1	142090
REPLACED TRIGGER GUARD, BOLT BODY AND LEFT & RIGHT BACKERS.	21072	\$19.47	10	135668
REPLACED BOLT STOP.	21072	\$21.99	3	1356557
REPLACED BOLT ONLY.	21072	\$19.47	6	136597
REPLACED BOLT ONLY.	21072	\$19.02	6	136580
REPLACED BOLT BODY.	21072	\$19.02	7	136556
REPLACED BOLT ONLY.	21072	\$21.04	6	136595
UPDATED BOLT STOP.	21072	\$19.47	2	142093
REPLACED REC. INSERT ASSY	21072	\$19.02	6	135908
CORRECTED BACKWARD INSTALLED BACKER.	21072	\$19.02	4	135628
TESTED OK. EXTRACTOR & EJECTOR & MAGAZINE ALL TESTED OK. REPLACED BOLT AND BACKERS.	21072	\$19.02	4	135698
REPLACED SCOPE, BOLT BODY, LEFT & RIGHT BACKERS AND BORESITED.	21072	\$25.09	8	135603