

Ref. #010204-000083

Serial #71002134

I bought this model 710 (30-06) Rifle yesterday, and the fit and finish are outstanding. However, the bolt action requires 2 men and a strong boy to work it (the action is very tight and not smooth like my old 30-06 Remington 700 BDL! Is there a fix for this problem?

V\R Bob Stephens (703)495-9327 robert.stephens@gte.net

Ref. #010214-000046

I am very interested in purchasing the new Mod.710. I looked at the rifle at a local store but found the bolt very stiff and hard to lock down when closing. With this stiffness relax after use or is it designed to be difficult to force the bolt lever down in the locked position?

Ref. #010214-000015

Serial #71003999

The safety release on my new 710 makes a foud click when it's released. Not noticable in the store where I purchased it, but quite obvious in the quiet of my shop. I'm concerned it may spook a buck within hearing range. How can it be silenced????

Ref. #010225-000042

Glad to see the model 710 developed and offered. Purchasing this affordable product will be an excellent way to introduce new shooters to the sport.

Do you have intentions of offsting this model in calibers suitable for youth shooting (.243Win. 7mm08)???

Ref. #010224-000069

Not a question, but an opinion Today at local dealer, examined and operated the new Model 710 ---- Am quite disappointed in function of same - even with lots of lubricant, the bolt binds and does not operate smoothly and without significant drag. Same opinion echoed by several other examiners of this model. Suspect this model will require some fine tuning by the manufacturer before enthusiastic sales are experienced. Respectfully, J.P. Tyson M.D.

Ref. #010305-00006

I have read some info on a new centerfire rifle (model 710). When I tried to find out about them from my local dealer they informed me that you had recalled them. I have not been able to find info out either way.

