

1. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700
 GENERAL CONDITION: NEW R #: 29996
 OUTSIDE WORK: FRONT TRIGGER ADJUSTING DATE: 1-4-71
SEAR WITH RE-ADJUSTED. FROM: LEFAYETTE SKI S.
 FIRED AMMO TYPE: - WINCHESTER 12 GA.
 & CONDITION: _____ GUN #: 6339151
 PROCP: RE-ONE INSR: 0 TEST: 98 CODE: DT-9170
 HEADING: O.K. SK/OIL: 3006
 BREECH OPENING: - CHECKED BY: C. PROVER
 RECOIL SHOULDERS: O.K. APPROVED: _____
 CHAMBER: O.K. APPROVED: _____
 TEST: N.O. APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____
NO DAMAGED OR BROKEN PARTS.

COMPLAINT: "SEVERAL TIMES GUN WENT OFF WHEN CLOSING BOLT."

INCIDENT: FOLLOWS DOWN

COMMENTS: SEAR-TRIGGER CONNECTOR ENGAGEMENT .005,
MINIMUM IS .015. THIS LETS THE SEAR SLIP OFF THE
CONNECTOR UNDER PRESSURE AND FELL ON DOWN
RESULTS.

PLAINTIFF'S
EXHIBIT

3283

1 of 1