## **BARBER - REM DOCSB0012172**

REPAIR UNDER WARRANTY REPAIR UNDER WARRANTY REPAIR AT 1/2 MSP REPAIR AT 1/2 MSP **BLM PROGRAM** REPAIR UNDER WARRANTY REPAIR @ 1/2 MSP **BLM PROGRAM** NEW TA SPECIAL PRICE NEW TA SPECIAL PRICE **BLM PROGRAM BLM PROGRAM BLM PROGRAM BLM PROGRAM BLM PROGRAM** REPAIR N/C NEW TA UNDER WARRANTY REPLACE TPA AT N/C RIFLE NEVER UPDATED REPLACE TPA AT N/C REPLACE TRIGGER ASSEMBLY AT SPEC PRICE CHECK OVER REPLACE TPA

Subject to Protective Order - Williams v. Remington