

4015	POORLY MAINTAINED	NY	CENTRE FIREARMS	
4039	NO FAULT FOUND,			
4006	ALTERED/ADJUSTED	WA	KYLE'S GUN SHACK	
4040	UNCONFIRMED	CT	FINNEGAN	J.J.
4039	NO FAULT FOUND	SC	WALTON	JAMES
4015	RUST IN TRIGGER ASSEM.	WA	SEATTLE PO. DEPT. MOELLENDORF	
4015	POOR MAINTENANCE	PA	BUDDY'S RV & SPORT SHOP	
4039	NO FAULT FOUND	TX	SMITH'S GUNS, INC.	
4039	NO FAULT FOUND	OK	HENDERSON	DON
4039	NO FAULT FOUND	TN	BOYER	BEN
4039	NO FAULT FOUND	PA	LAARMAN	ROBERT
4039	NO FAULT FOUND	MN	MIKSATKO	LOUIS
4040	UNEXAMINED	VT	KING	PHIL
4039	NO FAULT FOUND	MN	AHLMAN'S	
4006	ADJUSTED OUTSIDE OF FACTORY	GA	BUTTERY	HOWARD
4006	ADJUSTED	MN	MAGEE	KEVIN
4015	POORLY MAINTAINED	CO	GUZY	DAVID
4006	ALTERED/POORLY			
4015	MAINTAINED	NY	MORALES	DIORIS
4006	ALL 3 TRIG. ADJUSTMENT SCREWS HAD BEEN RE-SET	FL	D & M GUN WORLD, INC.	
4039	NO FAULT FOUND	NY	WOOD	MICHAEL
4015	IMPROPER MAINTENANCE	MO	ASHCROFT	J. ROBERT
4006	GUN HAS BEEN TAMPERED WITH	OH	MAYER	MARK
4015	VERY POORLY MAINTAINED	MD	ROBINSON	WILLIE