

Ken Nickeson

From: GRANT LAVELLE
Sent: 11/04/2004 09:15:18 PM
To: snipersonline@list1.netnet.net
CC:
BCC:
Subject: [snipersonline] SLAM FIRES ON REMINGTONS

My team had the same problem with our Remingtons. But before everyone starts going off on Remingtons the same thing happened on our FN's. The cause in both cases were triggers being set out of spec (ie way too light). In the case of our Remingtons we sent them to Charlie Milazzo and Charlie did a fabulous job on them. The situation worked out great for us in the long run as we ended up with new stainless barrels trued and sweet shooting. The FN's we sent back to FN and the triggers were set to minimum specs. Since then over the last 1.5 years we have not had any problems with either. I however had problems with my person 700 with a slam fire. I didn't use it for team work at the time and took the trigger out and found it was just filthy. Once cleaned I had no problems with the gun. Dirty Triggers and underweight triggers are just an accident waiting to happen my friends. I suggest you keep your trigger clean and keep the trigger within ASA and Company specs (if it's a factory trigger). I would also suggest you take your weapon in to a respected weapons armorer for periodic inspections. The cost of check ups are nothing in comparison to the cost of a slam fire that could have been avoided.

Grant
Joplin SRT

Express yourself instantly with MSN Messenger! Download today - it's FREE!
<http://messenger.msn.click-url.com/go/onm00200471ave/direct/01/>