

Bolt-Action Rifle "Lays Left" Issue

OBJECTIVE: Quality Issue

Action: Engineering and Quality to provide a brief overview of implementation of corrective action on issues uncovered by team.

· Process in place to make sure barrels are straight.

Eliminated 2/3's of issue by squaring receiver with new CNC H&S Precision to build to our print; barrel channel and action screws must be in line. Team is continuing to monitor and improve. Will remove from subsequent agendas.

Model 700/Seven Trigger Pull Weights

**OBJECTIVE: Quality Issue** 

Sales and Marketing are receiving a great deal of feed back from customers and consumers that we are losing sales at a devastating level to the Savage Accutrigger offerings.

Action: M700/7 Trigger Pull- Set pull at final assembly to 4 ½ to 5 ½ pounds. Ilion

engineering to report on implementation at final assembly.

Action: D. Diaz to evaluate fluted firing pin and report status at next meeting.

Model 7400 Improvement Project

OBJECTIVE: Quality Issue

ACTION: Trull to update team on comments and commitments from IWA

ACTION: Ilion to update on status and implementation dates. MUST HAPPEN FOR

WINTER PROGRAM!

ACTION: Discuss Model number change and strategy for regular catalog line. Model

7500 Woodmaster?

Need new model name, sku, etc.

Change to straight comb?

## **R&D TOPICS**

## E-Town Development Topics

• Model 597 Performance Improvement

OBJECTIVE Performance Improvement of 597

Action: EET on 10 round box was positive. Marketing approved taller box bottom on 10 round box. Diaz to provide update on DAT and target production date.

15 rounds per guin, 20 ammunition types. Overall malfunction rate of 1.3% would be lower however Federat has a GL that is .050" shorter than SAAMI. Must get tooling in for boxes sooner than 11 weeks quoted. R&D to transmit drawings.

17 Hornady Mach 2 Project

○BJECTIVE: New Product

Action: Disquiss M504 strategy and M597 strategy for this new cartridge. Need to have shippable product in the warehouse in September this year.

Action: Marketing needs confirmation on M504 product for intro at rep principles meeting.

C:\Program Files:\CDI\CrackerLoaderREM\REMEmail\rawblob\20060107010019A00084946.docPage 8

6/12/2006