

742

We apologize for the inconvenience. Following are some sources for repair of older Remington models. We no longer house any parts for this model. It may be difficult for local gunsmiths to find parts for obsolete models. For your convenience we have included a link below to a list of establishments that may offer parts or services for your older Remington firearm:.

http://www.remington.com/support/parts/obsolete http://

Schumaker Gunsmithing 1807 19th St Parkersburg, WV 25101 304-485-8771

Mann & Son Sporting Goods 515 W Water St. Pinckneyville, IL 62274 Phone: 618-357-2911 Fax: 618-357-3658

600 Parts or firearms

Thank you for your interest in Remington products. Appossible source for the Model 600 and parts for this model follows.

Mart's Customs 866-203-2649 59B Cookeville Hwy Carthage, TN 37030

Additional sources for finding older models follow:

gunsamerica.com auctionarms.com : gunfinder.net

To remove the bolt on the Model 600:

Thank you for contacting Reministen Country. To remove the bolt, push safety forward to unlock the bolt and raise bolt handle. Pull the bolt rearward. Press down on the front of the bolt stop. The bolt stop is located in the left rear of the bolt channel in the receiver. Use a small flat key or screw driver. Allow the bolt to slide back and disassemble as bolt stop is passed. Lift bolt from the rifle.

If you will complete the form located through the link below we will forward to you a copy of the original owners manual.

http://www.remingten.com/whatsnew/readroom.htm