

**IN THE UNITED STATES DISTRICT COURT
FOR THE DISTRICT OF OREGON
PORTLAND DIVISION**

TERI SEE and DARREL SEE,

No. 3:13-cv-01765-BR

Petitioners ,

vs.

**REMINGTON ARMS COMPANY,
LLC.,** A Delaware Limited Liability
Company, and **SPORTING GOODS
PROPERTIES, INC.,** A Delaware
Corporation

**PETITION FOR RELIEF FROM
JUDGMENT TO REMEDY FRAUD ON
THE COURT**

Defendants.

**EXHIBIT 11
3/21/1975 PRODUCT DEFICIENCIES MEMO**

OPERATIONS COMMITTEE

FIREARMS - TRAPS

MINUTE #6 - 1975

P. H. BURDETT
J. P. McANDREWS
E. SPARRE - E. HOOTON, JR.
H. M. STOESSEL
J. G. WILLIAMS
R. A. PARTNOY
E. F. BARRETT
E. B. BEATTIE
L. FOX
L. J. SCOTT

F. E. MORGAN
R. C. MAY
R. L. HALL
J. H. HODGSON
A. J. HERMANDORFER
W. E. LEEK
D. S. FOOTE
T. J. SHARPE
J. H. SWEENEY

COPY NO. Book

OPERATIONS COMMITTEE
ILION DIVISION

MARCH 21, 1975

PRESENT:

Committee

J. P. McANDREWS, CHAIRMAN
E. SPARRE
E. F. BARRETT
J. G. WILLIAMS
E. B. BEATTIE
L. FOX
J. H. SWEENEY, SECRETARY

Others

E. HOOTON, JR.
H. D. ALBAUGH
F. T. MILLENER
R. W. STEELE
L. J. SCOTT
R. B. SPERLING
R. L. HALL
C. B. WORKMAN
W. E. LEEK
J. P. LINDE
J. S. MARTIN

The meeting convened at 9 a.m. at Ilion.

NOT FOR REPRODUCTION
OR FURTHER DISTRIBUTION

REM 0027643

MINUTE #6 - 1975

-5-

March 21, 1975

C
H
A
P
A

Product deficiencies known or suspected in 1975 - Exhibit 15.

[REM 0028349]

[REM 0027644]

MINUTE #6 - 1975

-7-

March 21, 1975

BUSINESS MEETING - contd.

RESEARCH PERFORMANCE

In response to product deficiencies reported by Marketing, R & D made the following reply:

- . Model 700 three position Safety - development of this feature is in progress.
- . Model 786 Bolt Handle failures - a revised design for Bolt Handle attachment is in test.

The R & D report on progress versus schedule follows:

Program

Release Design
Schedule

[REM 0028221]

[REM 0027645]

REMINGTON PRODUCT DEFICIENCIES KNOWN OR SUSPECTED

C
H
A
P
A

[REM 0028350]
[REM 0027664]

EXHIBIT

E. M/700 SAFETY

- * EASE OF OPERATION AND SAFE GUN HANDLING DEMAND A DESIGN THAT ENABLES THE SHOOTER TO OPERATE THE ACTION WITH THE SAFETY "ON".

[REM 0028223]

[REM 0027665]

EXHIBIT 15

PRODUCT DEFICIENCIES (KNOWN OR SUSPECTED) 1975

Remington 3200 -

Model 1100 -

Model 1100 and 870

Model 742 -

Model 700 - three position safety would be desirable.

Model 788 - bolt handle breakage.

[REM 0026214]

[REM 0027621]

EXHIBIT 16