

Not sure what the test involves, I will do everything possible to have returnable and reliable guns at the end of the test. Also I have some gun right now that could be returned. I have 7- 30.06 rifles that were sent for the first safety dent test that was never done and I have 6- 30.06 & 6- 270 rifles that were not shot but were drop tested (one with a stripped receiver take-down screw hole).

Phillip

-----Original Message-----

From: Chamblee, Danny

Sent: Friday, March 12, 2004 1:24 PM

To: Reesor, Phillip K.

Cc: Boyles, Derek; Carrington, John M.; Golemboski, Matt R.

Subject: FW: 710 Receiver Insert Test

Phillip,

Charge account 8230150 Cost Center 28200. When can we expect the guns back? Also can we expect these to be guns that can be sold to customers (i.e. low # of rounds with no destructive tests)? We are in a backorder inventory position with 710s.

If you need any additional information, please let me know.

Thanks,

Danny Chamblee

Accounting Manager

Remington Arms Company, Inc.

Mayfield Plant

22 Rifle Trail, PO Box 99

Hickory, Ky 42051

Tel: (270)856-4210

Fax: (270)856-3233

E-Mail: danny.chamblee@remington.com

Visit Remington on the Web at remington.com

-----Original Message-----

From: Chamblee, Danny

Sent: Friday, March 12, 2004 9:25 AM

To: Reesor, Phillip K.

Cc: Boyles, Derek; Byrd, Shane R.; Roudabush, Kathy

Subject: 710 Receiver Insert Test

Phillip,

We need an SNC order for 20 710 Receiver Inserts part # F300401 and 10 30-06 Sku# 27410 to shop these parts to E-Town.

If you need any additional information, please let me know.

Thanks,

Danny Chamblee

Accounting Manager

Remington Arms Company, Inc.

Mayfield Plant

22 Rifle Trail, PO Box 99

Hickory, Ky 42051

Tel: (270)856-4210

Fax: (270)856-3233

E-Mail: danny.chamblee@remington.com

Visit Remington on the Web at remington.com

Subject to Protective Order - Williams v. Remington

BARBER - 5.30.060001548

ETE00000773