

- Model 7400 Woodmaster  
**NPP-2004-xx (To Be Assigned after discussion)**  
OBJECTIVE: New Product  
This stems from last meeting's discussion on the 7400 performance improvement/ 7400 Classic line. Our Trademark for Woodmaster is about to expire. Haven't used it since the 742. Great opportunity to create some buzz in the category, but we need to make sure the product demonstrates a marked improvement over current 7400 line. Last meeting's discussion lead to a concept that would allow Manufacturing to focus most of their attention to fine tuning the most popular calibers in the category. Trull would propose that the 7400 Woodmaster be a narrow line (2 or 3 sku's at most) that would have some tangible benefits over the current 7400 line (i.e. chrome chambers, Teflon e-nickel finish on internal components, better surface finishes on internal parts, etc) to give a performance edge to the line in order to establish a basis for staying in the category until a new gun is launched.
- Model 700 BDL SYN DEJ#8 (New Decorating Process)  
**NPP-2003-88 RAMAC 27507**  
OBJECTIVE: New Product  
Action: Trull to review concept for SHOT Show special and Ilion to advise on status of making sample run.

#### 2005 Prospective Ilion New Rifle Programs

- Model 700 Synthetic stock redesign  
**NPP-2005-xx**  
OBJECTIVE: Product Enhancement  
Action: Trull to provide direction for this program
- New Model 700 BDL SS Line  
**NPP-2005-xx**  
OBJECTIVE: Product Enhancement  
Action: Trull to provide direction for this program
- Revision/Replacement of Model 700 ADL SYN line  
OBJECTIVE: Product Enhancement in response to competitive conditions  
Action: Trull to provide direction for this program

#### Ilion Engineering Topics – Rifles

- Alternative Metal Finish for Stainless Rifles  
OBJECTIVE: Product Enhancement  
Action: Engineering to review status
- Roller Burnish for Rifle Chambers  
OBJECTIVE: Product Enhancement  
Engineering reported at last meeting that this process is being held up due to chamber eccentricity issues. Bulk of problem appears to rest with current CF heading process at Ilion.  
Action: Engineering to provide update.
- ISS Removal from Rifles  
Action: Trull to advise of discussion with Anne Cohen/Dale Wills.  
Action: Layout plan to implement.

#### Ilion Quality Issues – Rifles