

Remington Arms Co., Inc.

Subject: Bolt Action Centerfire Safety Message – Labor Reimbursement Schedule

Models 700 and 40-X

| | Clean and Inspect | Clean, Inspect and Bolt lock feature Removal | Fire control Replacement |
|---|---|--|-------------------------------------|
| Consumer payment to warranty center | \$20 | \$20 | \$20 |
| Remington Arms Co., Inc. payment to warranty center | \$10 | \$20 | \$20 |
| Paper Work to Consumer | 1. Coupon 2. Denial of Update – get back from customer | 1. Coupon 2. Notice of Operation | 1. Coupon 2. Notice of Operation |

Models 721 & 722

| | Clean and Inspect | Clean, Inspect and Bolt lock feature Removal | Fire control Replacement |
|---|---|--|---|
| Consumer payment to warranty center | \$20 | \$20 | N/A |
| Remington Arms Co., Inc. payment to warranty center | \$10 | \$20 | N/A |
| Paper work to Consumer | 1. Coupon 2. Denial of Update – get back from customer | 1. Coupon 2. Notice of Operation | Notify that gun has been sent back to factory |

Model 600, 660 and XP-100

| | Clean and Inspect | Clean, Inspect and Bolt lock feature Removal | Fire control replacement due to maintenance | Fire control Replacement due to recall |
|---|---|--|---|--|
| Consumer payment to warranty center | \$20 | \$20 | \$20 | Free |
| Remington Arms Co., Inc. payment to warranty center | \$10 | \$20 | \$20 | \$40 |
| Paper work to Consumer | 1. Coupon 2. Denial of Update – get back from customer | 1. Coupon 2. Notice of Operation | 1. Coupon 2. Notice of Operation | 1. Coupon 2. Notice of Operation |

Version 1

02-15-2002

1