BARBER - REM DOCSB0017485

Bolt Action Centerfire – Bolt Lock Update Modification Program. Website text

Model 788's are not part of this program. Should you desire service on your firearm please feel free to call us on our toll free service line @ 800 243.9709 and we will discuss with you the best way to obtain service or go to our repair section of this website to obtain service in the field

Bottom of page: History of firearm link// 10 commandments of safety and course//

6/12/2006 8