

FAULT CATEGORY	OLD CODE	NEW CODE	MALFUNCTIONS
OUT OF SPECS	M047	M217	OVER LOCKED
OUT OF SPECS		M218	PREPLAY ON SEAR NOT TO FACTORY SPECIFICATIONS
MISCELLANEOUS		M219	CARDBOARD PACKING RING WAS NOT REMOVED
MISCELLANEOUS		M220	PISTON/PISTON SEAL INCORRECTLY INSTALLED
OUT OF SPECS		M221	RECEIVER FEED CUTS ARE ROUGH
MISCELLANEOUS		M222	MODIFY TUBE CAPACITY TO ACCEPT 10 ROUNDS
BROKEN PART		M223	ACTION TUBE RING BROKEN
OUT OF SPECS	M059	M224	BREECH PLUG FROZE IN BREECH
BROKEN PART	M030	M225	EJECTOR SPRING IS BROKEN
OUT OF SPECS		M226	FORE END TUBE NUT IS LOOSE - FORE END RUBS BARREL
BROKEN PART	M061	M227	GAS BLOCK SEPARATED FROM BARREL
BROKEN PART		M228	GUIDE RING SEPARATED FROM BARREL
OUT OF SPECS		M229	MAGAZINE GUIDE IS OUT OF POSITION
BROKEN PART		M230	LOCKING BAR ASSEMBLY BROKEN
OUT OF SPECS		M231	NIPPLE NOT TO FACTORY SPECIFICATIONS
OUT OF SPECS		M232	RECEIVER INSERT IS MISSING
OUT OF SPECS	M055	M233	RESIZE BORE
BROKEN PART	M036	M234	RECEIVER BROKEN AT BARREL CLAMP
OUT OF SPECS	M055	M235	RESIZE BORE
BROKEN PART	M036	M236	RECEIVER BROKEN AT BARREL CLAMP