					- 2000000 - 20000000 - 200000000
FAULT CATEGORY	OLD CODE	NEW CODE	MALFUNCTIONS		MODELS
BROKEN PART	M011	M146	FORE END CRACKED		
BROKEN PART		M150	GRIP CAP IS DAMAGED		ecc.
BROKEN PART		M151	ACTION BAR IS BROKEN		
BROKEN PART		M153	RECEIVER PLUG SCREWS BR	OKEN	
BROKEN PART	M025	M192	MAG LATCH BROKEN / SEPAR	ATED FROM HOUSING	3
BROKEN PART		M223	ACTION TUBE RING BROKEN	***************************************	
			ecc	^0000000000 ^0000000000 ^0000000000	
FAULT CATEGORY	OLD CODE	NEW CODE	MALFUNCTIONS	V	MODELS
OUT OF SPECS	M001	M101	ACCURACY	0000000	
OUT OF SPECS	M027	M104	CHAMBER ROUGH / RINGS / T	11666666666666666	
OUT OF SPECS	M064	M109	DAMAGES CASES, BULLETS (OR SHELLS	
OUT OF SPECS		M112	HEADSPACE IS EXCESSIVE		
OUT OF SPECS	M017	M113	MUZZLE DAMAGE	· · · · · · · · · · · · · · · · · · ·	
OUT OF SPECS	M032	M121	RECEIVER IS MISCUT		
OUT OF SPECS	M020	M124	SIGHTS OFF CENTER		
OUT OF SPECS	M028	M127	TRIGGER PULL IS OUT OF FA	CTORY SPECS.	
OUT OF SPECS	M058	M128	CHAMBER DIRTY RUSTY		
OUT OF SPECS		M130	HEADSPACE AT MINIMUM	CONTRACTOR AND	
OUT OF SPECS	B4040	M132	BLUING SALTS ARE BLEEDING	AROW METAL	
OUT OF SPECS	M048	M133	EXTRACTOR MISSING	v.··	
OUT OF SPECS	04040	M135	TRIGGER CONNECTOR BINDS RIFLING ROUGH / MISCUT / D.		
OUT OF SPECS	M040	M139 M154	RECEIVER SCOPE MOUNT HO		
OUT OF SPECS	M031		BOLT FACE / SHROUD DAMAC		
OUT OF SPECS	M041 M035	M155 M156	BORE IS HEAT CHECKED.	יבט	
OUT OF SPECS	M060	M161	EJECTOR STUCK IN BOLT		
OUT OF SPECS	M042	M163	FREEBORE MISCUT / MIN		
OUT OF SPECS	M039	M170	SCOPE MOUNT THREADS UP	SET IN DECEIVED	
OUT OF SPECS	M043	M173	BARREL BRACKET OUT OF PO		
OUT OF SPECS	1010-13	M174	BOLT STOP STICKS	JOHNON	
OUT OF SPECS	M049	M176	RETURNED FOR RECALL/UPD	ΔTF	
OUT OF SPECS	M065	255	STOCK NOT BEDDED PROPER		
OUT OF SPECS	M056	M178	TRIG ADJ SCREWS RESET, C		
MISCELLANEOUS	141000	M102	BALANCE OF FIREARM IS NEE		ROPER REPAIR
MISCELLANEOUS	M053	M105	CONSIGNED GUN		
MISCELLANEOUS		M106	COULD NOT DUPLICATE CUS	TOMERS COMPLAINT	
MISCELLANEOUS	M062	M107	CREDIT RETURN		
MISCELLANEOUS		M108	DAMAGE APPEARS TO HAVE	OCCURRED IN TRANS	ilT
MISCELLANEOUS	M050	M114	NO CORRESPONDENCE		
MISCELLANEOUS	M038	M115	NO FAULT FOUND AT BENCH		
MISCELLANEOUS	M045	M116	PACKING ERROR		
MISCELLANEOUS	M037	M123	SAFETY CONCERN, EXAMINE	D BY PRODUCT SERV	ICE
MISCELLANEOUS		M140	ACTION IS DIFFICULT TO OPE		
MISCELLANEOUS	M051	M175	ISS BOLT LOCKED IN THE "OF	EN" POSITION	
FUNCTION	M044	M110	FAILS TO FIRE		
FUNCTION	M010	M129	FAILS TO EXTRACT		
FUNCTION	M057	M131	LIGHT OR NO INDENT FROM F	IRING PIN	
FUNCTION	M033	M134	FAULTY MAGAZINE		
FUNCTION	MO09	M137	FAILS TO EJECT		
FUNCTION	M023	M138	WILL NOT FEED PROPERLY		
FUNCTION	**************************************	M141	EXTRACTOR IS CATCHING ON		
FUNCTION	M015	M142	MAGAZINE DIFFICULT TO LOA		
FUNCTION	BADDO	M160	EJECTOR DOES NOT HAVE EI	NOUGH TENSION	
FUNCTION	° M008 ≥	M172	CLOSES HARD OVER SHELL	CED CHARDINI ATT	
FINISH	8 88.	M111	FINISH IS DAMAGED ON TRIG	GER GUARD/PLATE	
FINISH	8886 88886a.	M117	POOR FINISH - BARREL POOR FINISH - FORE END		
FINISH S		M118 M119	POOR FINISH - FORE END POOR FINISH - RECEIVER (OF	DEDAME\	
FINISH	***************************************	M120	POOR FINISH - RECEIVER (OF	CT (CAIVIE)	
FINISH	MQ19	M120	RUSTED COMPONENT		
FINISH	M022	M126	STOCK MARRED		
1 11 W33G2FC1	THEORETE:	101120	O LOOK MINISTRED		