FAULT CATEGORY	OLD CODE N	NEW CODE	MALFUNCTIONS MOD	ELS
FINISH		M118	POOR FINISH - FORE END	
FINISH		M119	POOR FINISH - RECEIVER (OR FRAME)	
FINISH		M120	POOR FINISH - STOCK	
FINISH	M019	M122	RUSTED COMPONENT	
FINISH	M022	M126	STOCK MARRED	
BROKEN PART		M103	BUTT PLATE / RECOIL PAD IS BROKEN	
BROKEN PART	M021	M125	STOCK CRACKED	
BROKEN PART	191021	M136	EXTRACTOR IS BROKEN	
BROKEN PART	M005	M145	BOLT HANDLE FELL OFF, BOLT IS BROKEN	
BROKEN PART	11,1000	M153	RECEIVER PLUG SCREWS BROKEN	
Dittorial in the second				
FAULT CATEGORY	OLD CODE N	NEW CODE	MALFUNCTIONS MOD	ELS
OUT OF SPECS	M001	M101	ACCURACY	
OUT OF SPECS	M027	M104	CHAMBER ROUGH / RINGS / TEARS / TIGHT	
OUT OF SPECS	M064	M109	DAMAGES CASES BULLETS OR SHELLS	
OUT OF SPECS		M112	HEADSPACE IS EXCESSIVE	
OUT OF SPECS	M017	M113	MUZZLE DAMAGE	
OUT OF SPECS	M032	M121	RECEIVER IS MISCUT	
OUT OF SPECS	M020	M124	SIGHTS OFF CENTER	
OUT OF SPECS	M028	M127	TRIGGER PULL IS OUT OF FACTORY SPECS.	
OUT OF SPECS	M058	M128	CHAMBER 遊園業 RUSTY	
OUT OF SPECS	191000	M130	HEADSPACE AT MINIMUM	
OUT OF SPECS		M132	BLUING SALTS ARE BLEEDING FROM METAL	
OUT OF SPECS	M048	M133	EXTRACTOR MISSING	
OUT OF SPECS	IVIOTO	M135	TRIGGER CONNECTOR BINDS	
OUT OF SPECS	M040	M139	RIFLING ROUGH / MISCUT / DAMAGED	
OUT OF SPECS	191040	M144	ROLL MARKING VISIBLE INSIDE BORE	
OUT OF SPECS	M031	M154	RECEIVER SCORE MOUNT HOLES OFF CENTER	
OUT OF SPECS	M041	M155	BOLT FACE / SHROUD DAMAGED	
OUT OF SPECS	M035	M156	BORE IS HEAT CHECKED	
OUT OF SPECS	M060	M161	EJECTOR STUCK IN BOLT	
OUT OF SPECS	M042	M163	FREEBORE WISCUT / MIN	
OUT OF SPECS	M039	M170	SCOPE MOUNT THREADS UPSET IN RECEIVER	
OUT OF SPECS	M043	M173	SARREL BRACKET OUT OF POSITION	
OUT OF SPECS	191043	M174	BOLT STOR STICKS	
OUT OF SPECS	M065	M477	STOCK NOT BEDDED PROPERLY	
OUT OF SPECS	M056	M178	TRIG ADJ SCREWS RESET, CANNOT READJUST	
MISCELLANEOUS	101030	M102	BALANCE OF FIREARM IS NEEDED TO PERFORM PROPER REPAIR	,
MISCELLANEOUS	M053	M105	CONSIGNED GUN	
MISCELLANEOUS		M106	COULD NOT DUPLICATE CUSTOMERS COMPLAINT	
MISCELLANEOUS	M062	M107	CREDIT RETURN	
	IVIOUZ (S	M108		
MISCELLANEOUS MISCELLANEOUS	M050	M114	DAMAGE APPEARS TO HAVE OCCURRED IN TRANSIT NO CORRESPONDENCE	
MISCELLANEOUS	M038	M115	NO CORRESPONDENCE	
MISCELLANEOUS	M045	M116	PACKING ERROR	
MISCELLANEOUS	M037	M123	SAFETY CONCERN, EXAMINED BY PRODUCT SERVICE	
MISCELLANEOUS	IVIOJI	M140	ACTION IS DIFFICULT TO OPEN	
MISCELLANEOUS	M051	M175	SS BOLT LOCKED IN THE "OPEN" POSITION	
FUNCTION	M044	M110	FAILS TO FIRE	
FUNCTION	M010	M129	FAILS TO FIRE	
FUNCTION	M033	M134	FAULTY MAGAZINE	
FUNCTION	M009	M137	FAILS TO EJECT	
FUNCTION	M023	M138	WILL NOT FEED PROPERLY	
FUNCTION	INDEU SON	M141	EXTRACTOR IS CATCHING ON SHELL HEAD	
FUNCTION	M015	M142	MAGAZINE DIFFICULT TO LOAD	
FUNCTION	E IVIVIU	M160	EJECTOR DOES NOT HAVE ENOUGH TENSION	
FUNCTION	M008	M172	CLOSES HARD OVER SHELL	
FINISH	1419110	M111	FINISH IS DAMAGED ON TRIGGER GUARD/PLATE	
FINISH	***************************************	M117	POOR FINISH - BARREL	
FINISH	Au.	M118	POOR FINISH - FORE END	
FINISH		M119	POOR FINISH - PORE END	
1 11 4333453	119999999	IVIII	ILOOK FINIOH - MEDELVEN (ON LIVAIME)	