MODEL 700 continued

DATE OF CALL BACKS

700 17 Rem. Cal. Only all serial number with "C" and "Q" prefixes Serial numbers starting A658000 to B6302402 & B6302403 to C6354486 Also V6291911 to V6292802 V6292831 to V6292869

700 SS

Only with catalog numbers 6080,9714,9725,9723 and serial numbers starting with S670, S671 and S620. In the Month of June 1992

PROBLEMS

Some of the .17 cal Rem. Barrels could develop cracks and eventually split due to unique combination of characteristics. present only in barrels chambered for .17 Rem. Return to: Remington Arms

Some frigger connector missed washing & desburring process which could make the gun go off when closing the bolt.

Return to: Remington Arms

Subject to Protective Order - Williams v. Remington