RSTT	Rear sight tipped] 0
RSBR	Rear sight base raised	Ō
FSTR	Front sight raised	0
FSTL	Front sight loose	1 A0000 19000000000
RSTL	Rear sight loose	0
MGPT-G	Missing parts at target	1 0
UNCN-G	Uncoded nonconformity at target	j p
	hi-	0
AI-P	Assembly incompleye at proof	0
BC-P	Blows cases at proof	0
BEB-P	Barrel extension broken at proof] 0
BLP-P	Blanked primer at proof]
BP-P	Blown primer at proof	0
BS-P	Barrel split at proof	0
DLOS-P	Doesn't lock over shells at proof	1
ESB-P	Ejector sticks back at proof	Ö
FCB-P	Fore-end cracked at proof	0
FESO-P	Fore-end shot off at proof	D.
FF-P	Fails to fire at proof	9
GCSO-P	Gas cylinder shot off at proof	0
GRSO-P	Guide ring shot off at proof	D.
MCSO-P	Magazine cap shot off at proof	0
MSI-P	Magnaflux stamp illegible on bbt	0 0
MSM-P	Magnaflux stamp missing on bbl	0
PP-P	Pierced primer at proof	0
SCB-P	Stock cracked or broken at proof	ō
UNCM-P	Uncoded proof malfunctions	ō
***************************************	Onode production and the second production a	
3355555		
	.86.	
Subject to Protective Order	www.ams v. Hemington	