

I appreciate your input, but this is not just about this isolated incident. Thed asked Jerry yesterday to reconvene the group to discuss where we are with regard to the trigger pull issues we have been experiencing. As you no doubt remember, before leaving for S&K, we were struggling to get consistent trigger pulls at final assembly. We may have made some progress, but we are not there yet.


Thanks.

John

John W. Kelly

From: Orf, Robert J.		*********	tta. Allatan			
Sent: Thursday, January 1	2, 20067					
To: Perniciaro, Stephen; K	elly, John	W.;;Allen	Gerald R.;	Mroz, Jo	hn B.; Ben	nett, Gary
Subject: RE: Fire on Safe						
		10000				

The first order of business should be to took at what is wrong with the fire control ( if in fact the fire control is the problem) and find out who built it and get back with them about the problem.



Subject to Protective Order Williams v. Remington