SR	Shoulder rough		
SRC	Stems right side of chamber		
SRIC	Specific rings in chamber		
SSOC	Surface scratches on case		
SWH	Safety switch works too hard		
SWW	Safety Switch won't work		
TD	Tips down		
TU	Tips up		
TWP	Trigger won't pull		
TWR	Trigger won't retract	á	
UNCN-T	Uncoded	- स्	8
		.3333	386.
HI	High	****	
LO	Low	·	*****
LEFT	Left		2000
RIGHT	Right	30.000.000.000	
FSST	Front sight tipped	100000000000000000000000000000000000000	395.
RSTT	Rear sight tipped		
RSBR	Rear sight base raised		****
FSTR	Front sight raised	300 30 :3333:5	
FSTL	Front sight loose	22332	
RSTL	Rear sight loose	,388888	
MGPT-G	Missing parts at target		- 1
UNCN-G	Uncoded nonconformity at targ	et	å
BBB	Barrel bracket cracked or broke	en at proof	
BC-P	Blows cases at proof		
BEB-P	Barrel extension broken at pro-	of	_
BLP-P	Blanked primer at proof	333333	
BLSO-P	Barrel lug shot off at proof		_
BP-P	Blown primer at proof	300000000	
BS-P	Barrel split at proof		
DLOS-P	Doesn't lock over shells at pro-	of	
FCB-P	Fore-end cracked at proof	No.	
FESO-P	Fore-end shot off at proof	00°	
GCSO-P	Gas cylinder shot off at proof	<del>-</del>	_
MSI-P	Magnaftux stamp lilegible on b	bl	_
MSM-P	Magnattux stamp missing on b	bl	
PP-P	Pierced primer at proof		
SCB-P	Stock gracked or broken at pro	of	ᅦ
UNCM-P	Uncoded proof malfunctions	•••••	7

0

0 0

