

Remington Arms
MayfieldQuality Manual 6-2
Appendix A
Form C-1036

First Article Inspection -Mayfield Results

Part Number
Part Name201342
TRIGGER BLANKDrawing #
Rev. LevelD-201342
2Vendor
Date Received
Lot #ILION
5/30/00
N/A

200 pcs

SAMPLES						Average	Min	Max	
#	Feature Name	#1	#2	#3	#4	#5			
1	.166 +/- .004	0.164	0.165	0.163	0.165	0.163	0.164	0.163	0.165 mic
2	.135 +/- .004	0.134	0.134	0.133	0.134	0.134	0.134	0.133	0.134 mic
3	2.237 +/- .010	2.237	2.234	2.239	2.234	2.233	2.235	2.233	2.239 comp
4	.380 +/- .003	0.366	0.367	0.366	0.368	0.365	0.366	0.365	0.368 comp
5	.680 +/- .004	0.665	0.666	0.667	0.668	0.665	0.666	0.665	0.668 comp
6	1.324 +/- .006	1.321	1.323	1.323	1.320	1.319	1.321	1.319	1.323 comp
7	.250 +/- .005	0.253	0.256	0.252	0.254	0.253	0.254	0.252	0.256 comp
8	.125 +/- .003	0.128	0.129	0.128	0.129	0.127	0.128	0.127	0.129 comp
9	1.090 +/- .005	1.082	1.081	1.080	1.079	1.078	1.080	1.078	1.082 comp
10	.1259 +/- .0005	A	A	A	A	A	A	A	gage pin
11	.968 +/- .005	0.973	0.971	0.965	0.965	0.965	0.968	0.965	0.973
12	.188 +/- .005	0.185	0.186	0.186	0.187	0.185	0.186	0.185	0.187
13							#DIV/0!	0.000	0.000
14							#DIV/0!	0.000	0.000
15							#DIV/0!	0.000	0.000
16							#DIV/0!	0.000	0.000
17							#DIV/0!	0.000	0.000
18							#DIV/0!	0.000	0.000
19							#DIV/0!	0.000	0.000
20							#DIV/0!	0.000	0.000
21							#DIV/0!	0.000	0.000
22							#DIV/0!	0.000	0.000
23							#DIV/0!	0.000	0.000
24							#DIV/0!	0.000	0.000
25							#DIV/0!	0.000	0.000
26							#DIV/0!	0.0000	0.0000
27							#DIV/0!	0.0000	0.0000
28							#DIV/0!	0.0000	0.0000
29							#DIV/0!	0.0000	0.0000
30							#DIV/0!	0.0000	0.0000

Inspected By
Approved By
Rejected By

Scott Dick

6/2/00

Date
DateRevised By: M. Goelmboski
Revision Date: 2/14/00

FirstArticleInspection

ET06011