CONFIDENTIAL

Remington Arms Company Inc.

RESEARCH & DEVELOPMENT TECHNICAL CENTER
315 WEST RING ROAD
ELIZABETHTOWN, KY 42701

M/710 Testing "Holeless" Connector and Tempered Scope Mount Screw Test

Description:

Mayfield and E-town Firearm Design personnel proposed eliminating the hole in the connector for the M/710 since it serves no function in this model. This simplifies manufacture and results in a less expensive part. Mayfield and E-town Test jointly agreed on a 15 gun test where 8 rifles would be built in .30-06 caliber and 7 in .270 Win. Caliber. About this same time Mayfield had a need to test a heat treat change to the scope mount screws also used on the 710. It was decided to test both of these changes concurrently.

A test outline was agreed to that consisted of the following measurements and tests:

- Measurements as Rec'd (All 15 guns)
 - Trigger Pull (specific 4.0 5.5 lbs.)
 - o Engagement (spec. is .020 .025 in.)
 - Over travel (spec. is .20 + .025 iπ.)
 - Headspace
- Proof and Re-measure Headspace (All 15 guns)
- SAAMI Jar-Off, Drop Rotation (6 guns: 3 of each cal. chosen at random)
 - o Drop with scopes mounted (Use std. Screws)
 - o Set fire controls to process minimums

TRIGGER PULL 4.0 lbs.
ENGAGEMENT 0.020 in.

- Extended SAAMI Jars Off Only (same 6 guns) For Information Only
 - o Drop with scopes mounted (Use std. Screws)
 - Set fire controls to process minimums

TRIGGER PULL: 4.0 lbs. ENGAGEMENT: 0.020 in.

- 100 Rd. Jack Fen. Test (9 guns)
 - Shoot with scopes mounted on 8 guns, 9th gun has no scope mounted
 - Use special mount screws provided (tempered screws)
 - Use Loctite 222MS and torque screws to 15 20 in. lb.
 - Fire 100 rds/gun, heavy shooting jacks (any ammo-note what's used)
 - Track malfunctions
 - Pay special attention to fire control function and feel
 - © Cycle Safety from Fire to Safe every feeding cycle
 - Check Scope mount screws for tightness after firing 100 rds
 - Remove and inspect screws for cracks after firing

April: 02 – M.710 Testing – "Holeless" Connector and Tempered Scope Mount Screw Test; R & D Technical Center Project No. 241230; TLW 0822 file: C::Program:[Files:TCDI:CrackerLoaderREM:REMEmail:rawblob:20060120103807A00009995.doc

Page 1
CONFIDENTIAL

S. FRANZ Rev. 1.0-052476 0.48444