## 2<sup>NO</sup> SHIFT OPERATION REPORT REMINGTON ARMS, INC. DATE: 1/03/05

SAFETY:

PERSONNEL;

DEPT. 8761;

DEPT. 8768;

DEPT. 8772;

**DEPT. 9131**;

DEPT. 9132;

OPERATIONS;

8761;

## RIM FIRE;

NO ACTIVITY; WE NEED F91540M BARRELS AND F9996L RECEIVERS TO GET STARTED

FINISHED BUILDING THE 5145'S THAT WE HAD PARTS BUILT-UP FOR WE NEED MORE OF THE F97840 RECEIVERS TO CONTINUE WORKING ON THE 5145'S AS WELL AS THE 5153'S. WE HAVE PLENTY OF PARTS TO FINISH THE 7087'S AND THEY APPEAR TO BE SOME OF OUR OLDER ORDERS. V. PESCATORE WORKED ON REPAIRS ALL NIGHT.

TPA'S;

## 700 FIRE CONTROL;

WE ARE FINDING SAFE-ARMS THAT HAVE MISALIGNED HOLES THAT WILL NOT ALLOW PINNING TO FIRE CONTROL

700 BUILD + STK ACTIONS	RIMFIRES	NEW GEN	WAREHOUSE
**************************************			11:30P.M.
	0	60	