TD	Tips down
TU	Tips up
TWP	Trigger won't pull
TWR	Trigger won't retract
UNCN-T	Uncoded
XH	Extracts hard
HI	High
LO	L.ow
LEFT	Left
RIGHT	Right
DG	Doesn't Group
FSST	Front sight tipped
RSTT	Rear sight tipped
RSBR	Rear sight base raised
FSTR	Front sight raised
FSTL	Front sight loose
RSTL	Rear sight loose
MGPT-G	Missing parts at target
UNCN-G	Uncoded nonconformity at target
Al-P	Assembly incompleye at proof
BBB	Barrel bracket cracked or broken at proof
BC-P	Blows cases at proof
BEB-P	Barrel extension broken at proof
BLP-P	Blanked primer at proof
BLSO-P	Barrel lug shot off at proof
BP-P	Blown primer at proof
BS-P	Barrel split at proof
DLOS-P	Doesn't lock over shells at proof
ESB-P	Ejector sticks back at proof
FCB-P	Fore-end cracked at proof.
FESO-P	Fore-end shot off at preof
FF-P	Fails to fire at proof
GCSO-P	Gas cylinder shot off at proof
MSI-P	Magnaflux stamp legible on bbl
MSM-P	Magnaflux stamp missing on bbl
PP-P	Pierced primer at proof
SCB-P	Stock cracked or broken at proof
UNCM-P	Uncoded proof malfunctions
-11AIAL	Tallana and decision them millionizations.

0 0

0

