

NEW RECEIVER INSERT\HANSON 100.job: Histogram 3 - X

Part Program	NEW RECEIVER INSERT		
Description	HANSON 100		
Feature name	ENGAGEMENT		
Feature number	00897		
NOM	-0.8670	UTL	-0.8620
		LTL	-0.8720
Lot Size	100		
Mean	-0.8661	Std Dev	0.0001
Mean+3S	-0.8658	Mean-3S	-0.8664
Skew	-0.0457	Kurtosis	-16.3518
Minimum	-0.8664	Maximum	-0.8659
Range	0.0005	Avg Range	0.0002

	Number	Percent
Acceptable Parts	100	100.0
Defectives Lower	0	0.0
Defectives Upper	0	0.0
Defectives Total	0	0.0

	Deviation Method	Range Method
QU	37.50	18.37
QL	53.42	26.17

Cp	15.19	Cpk	12.42
----	-------	-----	-------

ET06021