

NEW RECEIVER INSERT\HANSON 100.job: Histogram 3 - PS

Part Program NEW RECEIVER INSERT
 Description HANSON 100
 Feature name ENGAGEMENT
 Feature number 00897
 NOM 0.0000 UTL 0.0100 LTL -0.0100
 Lot Size 100
 Mean 0.0044 Std Dev 0.0004
 Mean+3S 0.0054 Mean-3S 0.0033
 Skew -0.1262 Kurtosis -0.9384
 Minimum 0.0036 Maximum 0.0051
 Range 0.0015 Avg Range 0.0005

	Number	Percent
Acceptable Parts	100	100.0
Defectives		
Lower	0	0.0
Defectives		
Upper	0	0.0
Defectives		
Total	0	0.0

	Deviation Method	Range Method
QU	15.73	11.57
QL	40.15	29.52

Cp 5.58 Cpk 5.58

ET06024