

First Article Inspection - Mayfield Results

Part Number
Part NameF 300365
Box BOTTOMDrawing #
Rev. LevelD - 300365
24Vendor
Date Received
Lot #PAR 4
7/6/00

(CAVITY # 1)

SAMPLES						Average	Min	Max	
#	Feature Name	#1	#2	#3	#4	#5			
1	1.244 ± .005	1.241	1.240	1.240	1.241	1.241	#DIV/0!	0.0000	0.0000
2	3.824 ± .005	3.818	3.819	3.819	3.819	3.818	#DIV/0!	0.0000	0.0000
3	2.75 ± .005	2.66	2.68	2.69	2.72	2.67	#DIV/0!	0.0000	0.0000
4	3.505 ± .005	3.500	3.500	3.503	3.503	3.501	#DIV/0!	0.0000	0.0000
5	3.665 ± .005	3.662	3.664	3.662	3.665	3.661	#DIV/0!	0.0000	0.0000
6	.788 ± .005	.783	.784	.784	.784	.784	#DIV/0!	0.0000	0.0000
7	1.016 ± .005	1.018	1.014	1.015	1.012	1.017	#DIV/0!	0.0000	0.0000
8	.046 ± .005	.043	.044	.045	.043	.043	#DIV/0!	0.0000	0.0000
9	.040 ± .005	.043	.043	.042	.043	.042	#DIV/0!	0.0000	0.0000
10	.512 ± .005	.507	.508	.506	.508	.500	#DIV/0!	0.0000	0.0000
11	2.810 ± .005	2.808	2.807	2.807	2.806	2.807	#DIV/0!	0.0000	0.0000
12	2.590 ± .005	2.585	2.585	2.588	2.587	2.587	#DIV/0!	0.0000	0.0000
13	.040 TYP	.043	.043	.045	.048	.045	#DIV/0!	0.0000	0.0000
14	.322 TYP	.318	.318	.318	.319	.318	#DIV/0!	0.0000	0.0000
15	.372 TYP	.374	.377	.377	.373	.374	#DIV/0!	0.0000	0.0000
16	.470 TYP	.472	.474	.474	.475	.471	#DIV/0!	0.0000	0.0000
17	.140 ± .005	.143	.143	.142	.141	.143	#DIV/0!	0.0000	0.0000
18	.100 ± .005	.096	.094	.099	.100	.101	#DIV/0!	0.0000	0.0000
19	1.104 ± .005	1.105					#DIV/0!	0.0000	0.0000
20	.015 ± .005	.017	.014	.015	.013	.014	#DIV/0!	0.0000	0.0000
21	3.732 ± .005	3.734					#DIV/0!	0.0000	0.0000
22	.056 ± .005	.055					#DIV/0!	0.0000	0.0000
23	.132 ± .005	.128					#DIV/0!	0.0000	0.0000
24	3.650 ± .005	3.646					#DIV/0!	0.0000	0.0000
25							#DIV/0!	0.0000	0.0000
26							#DIV/0!	0.0000	0.0000
27							#DIV/0!	0.0000	0.0000
28							#DIV/0!	0.0000	0.0000
29							#DIV/0!	0.0000	0.0000
30							#DIV/0!	0.0000	0.0000

* see
sepa
sheetInspected by
Approved By
Rejected ByDate
DateRevised By: M. Goelmboski
Revision Date: 2/14/00

FirstArticleInspection

ET06287