

GUN - A - 4
DATE - 10-31-00
SHOOTER - JT/SL

M/710 JACK FUNCTION

PROJECT# 241095
TLW 0344

AMMO TYPE - REM R30065 180GR			LOT# -	
MALFUNCTIONS			MALFUNCTIONS	
1	1		51	3
2	2		52	4
3	3		53	1
4	4		54	2
5	1		55	3
6	2		56	4
7	3		57	1
8	4		58	2
9	1		59	3
10	2	HS +.002	60	4
11	3		61	1
12	4		62	2
13	1		63	3
14	2		64	4
15	3		65	1
16	4		66	2
17	1		67	3
18	2		68	4
19	3		69	1
20	4		70	2
21	1		71	3
22	2	SL	72	4
23	3		73	1
24	4		74	2
25	1		75	3
26	2		76	4
27	3		77	1
28	4		78	2
29	1		79	3
30	2		80	4
31	3		81	1
32	4		82	2
33	1		83	3
34	2		84	4
35	3		85	1
36	4		86	2
37	1		87	3
38	2		88	4
39	3		89	1
40	4		90	2
41	1		91	3
42	2		92	4
43	3		93	1
44	4		94	2
45	1		95	3
46	2		96	4
47	3		97	1
48	4		98	2
49	1		99	3
50	2		100	4

Took pictures of mag box
Follower sticking
Filed sides.

Page 1

TOTAL RDS - 100

ET06686

GUN - A-4
DATE - 10-31-06
SHOOTER - Jell R

M/710 JACK FUNCTION

PROJECT# 241095
TLW 0344

100

AMMO TYPE - REM R30065 180GR		LOT# -	
MALFUNCTIONS		MALFUNCTIONS	
1	1	51	3
2	2	52	4
3	3	53	1
4	4	54	2
5	1	55	3
6	2	56	4
7	3	57	1
8	4	58	2
9	1	59	3
10	2	60	4
11	3	61	1
12	4	62	2
13	1	63	3
14	2	64	4
15	3	65	1
16	4	66	2
17	1	67	3
18	2	68	4
19	3	69	1
20	4	70	2
21	1	71	3
22	2	72	4
23	3	73	1
24	4	74	2
25	1	75	3
26	2	76	4
27	3	77	1
28	4	78	2
29	1	79	3
30	2	80	4
31	3	81	1
32	4	82	2
33	1	83	3
34	2	84	4
35	3	85	1
36	4	86	2
37	1	87	3
38	2	88	4
39	3	89	1
40	4	90	2
41	1	91	3
42	2	92	4
43	3	93	1
44	4	94	2
45	1	95	3
46	2	96	4
47	3	97	1
48	4	98	2
49	1	99	3
50	2	100	4