

B-4 - DYNAMIC DUST/DEBR. V PRIMED CASE FIRED * 1 V ** 2 FAIL TO FEED DISASSEMBLED -BLOWN OUT & RE-ASSEMBLED FOLLOW DOWN ON SECOND ROUND-ICUMINATED TOOL . Sear Came up BUT NOT ENOUGH TO ACCOW CONN. TO COME UP UNDER THE SEAR

ATFEMPTE TO

MOVED SAFETY TO SAEF

POSITION TO FORCE

SEAR UP. UNABLE TO

MOVE SAFETY FULLY TO

SAFE POSITION.

LOWERED F.P. TO FULL

FORWARD POSITION

ATTEMPTED 2nd TIME
THE TIME SAFE MOVED
TO SAFE ON POSITION.
AND TRIGGER BOND CONN
RETURNED TO PROPER
RELATIONSHIP UNDER SEAR.