

CAL.- 30.06

#3

PROJECT#241095

NAME		DATE	TEST ACTIVITY	COMMENTS	ROUNDS AT START: 0	RDS. FIRED	TOTAL RDS.
JA/SW	12/8/00	Preliminary Measurements (Done)					
Jesse	12/10/00	Function Check of IR system (Pass)					
Jesse	12/11/00	Tacit Function Test 100 Rd Level				100	100
JA/SW	12/12/00	Clean & Inspect					
MSH	12/14/00		MURDER SPILL FOR BOX RECORD				
"	"		MURDERED BOX BORROW				
Jesse	12-19-00	Tacit Function Test 400 Rd/1				400	500
Jesse	12/15/00	Clean & Inspect					

Coverpg :

ET07411

Confidential - Subject to Protective Order
Williams v. Remington

Remington Arms Company Inc.
RESEARCH & DEVELOPMENT TECHNICAL CENTER
315 WEST RING ROAD
ELIZABETHTOWN, KY 42701

Clean & Inspect Checklist, Series C T&P

Model: 710

Project: 241095

Rifle: C-12

TLW #: TLW0300

Date: 12 / 15 / 00

Inspector: Jesse

Round Level: 500

☒ Measure Headspace Min + .002

☒ Sear Engagement: .0250

☒ Trigger Pull: 1st 4.0 2nd 4.5 3rd 4.0

Ave. 4.17
~~4.17~~

Check the following areas for signs of unusual wear or breakage:

- ☒ Receiver insert
- ☒ Rear surface of Bolt Lugs
- ☒ Check for "galling" on rear of Bolt Lugs
- ☒ Bolt Plug
- ☒ Bolt Plug Insert "ears" on firing pin assembly
- ☒ Check for loose or missing pins - make note and re-stake if necessary
- ☒ Check plastic inserts for cracks or other damage.
- ☒ Firing Pin Head for Looseness.
- ☒ Check Firing Pin Tip for Looseness.
- ☒ Check Take Down Screws for Movement. Show new position relative to original mark.

 Rear  Middle  Front

Position after re-torque:

 Rear  Middle  Front

☒ Check Diaz Bracket Screw for looseness. _____

☒ Check Bolt Stop slight rotational movement

Take digital photographs, if appropriate, to record unusual wear, damage or other note-worthy observations. List the digital file name for reference along with any comments below. _____

TLW0300

TESTPLAN_Rev1_C_Series.doc

Remington Confidential

Revision # 1

ET07412